

**Urgent
FIELD CORRECTIVE NOTICE**

March 19, 2012

- Account #-

-Customer Address-

Voluntary Recall # 2012-0014 COMBO REAMER DRILL

Dear Stryker Customer,

Stryker® Osteosynthesis is initiating a Voluntary Recall of the Combo Reamer Drill which was manufactured from Nov. 26th 2010 until Nov. 17th 2011 and is included in the following article numbers and comprehends the lots as listed below:

Table 1: Distribution list

Article number	Article name	Lot#	Number of devices
704006	Combination Reamer Assembly Omega SHORT	X11939	
704006	Combination Reamer Assembly Omega SHORT	X25533	
Summation			

Article number	Article name	Lot#	Number of devices
704005-10	Combo Reamer Drill	X20174	
704005-10	Combo Reamer Drill	X22771	
704005-10	Combo Reamer Drill	X29905	
Summation			

Article number	Lot#	Distributed in:	Kit Ref#	Kit Lot#	Number of devices
704005	W34411	Instrument Set Omega 3	990263	W35033	
704005	W37630	Instrument Set Omega 3	990263	X03620	
704005	X05215	Instrument Set Omega 3	990263	X06186	
704005	X05749	Instrument Set Omega 3	990263	X10987	
704005	X05751	Instrument Set Omega 3	990263	X06186	
704005	X07692	Instrument Set Omega 3	990263	X10987	
704005	X07695	Instrument Set Omega 3	990263	X10987	
704005	X07696	Instrument Set Omega 3	990263	X10987	
704005	X07697	Instrument Set Omega 3	990263	X10987	
704005	X09625	Instrument Set Omega 3	990263	X10987	
Summation					

Article number	Article name	Lot#	Number of devices
704005	Combination Reamer Assembly Omega STANDARD	W34410	
704005	Combination Reamer Assembly Omega STANDARD	W37630	
704005	Combination Reamer Assembly Omega STANDARD	W38887	
704005	Combination Reamer Assembly Omega STANDARD	X00014	
704005	Combination Reamer Assembly Omega STANDARD	X00032	
704005	Combination Reamer Assembly Omega STANDARD	X00500	
704005	Combination Reamer Assembly Omega STANDARD	X05215	
704005	Combination Reamer Assembly Omega STANDARD	X05749	
704005	Combination Reamer Assembly Omega STANDARD	X05752	
704005	Combination Reamer Assembly Omega STANDARD	X07693	
704005	Combination Reamer Assembly Omega STANDARD	X07694	
704005	Combination Reamer Assembly Omega STANDARD	X09624	
704005	Combination Reamer Assembly Omega STANDARD	X09625	
704005	Combination Reamer Assembly Omega STANDARD	X11934	
704005	Combination Reamer Assembly Omega STANDARD	X11935	
704005	Combination Reamer Assembly Omega STANDARD	X14821	
704005	Combination Reamer Assembly Omega STANDARD	X14826	
704005	Combination Reamer Assembly Omega STANDARD	X14827	
704005	Combination Reamer Assembly Omega STANDARD	X18594	
704005	Combination Reamer Assembly Omega STANDARD	X20168	
704005	Combination Reamer Assembly Omega STANDARD	X23220	
704005	Combination Reamer Assembly Omega STANDARD	X23318	
704005	Combination Reamer Assembly Omega STANDARD	X24344	
704005	Combination Reamer Assembly Omega STANDARD	X27821	
704005	Combination Reamer Assembly Omega STANDARD	X30015	
704005	Combination Reamer Assembly Omega STANDARD	X30646	
704005	Combination Reamer Assembly Omega STANDARD	X31275	
704005	Combination Reamer Assembly Omega STANDARD	X31276	
704005	Combination Reamer Assembly Omega STANDARD	X32729	
704005	Combination Reamer Assembly Omega STANDARD	X32730	
704005	Combination Reamer Assembly Omega STANDARD	Z00136	
704005	Combination Reamer Assembly Omega STANDARD	Z00137	
Summation			

Issue

Stryker Osteosynthesis has become aware of the fact that the cutting performance of the Combo Reamer Drill might be not as expected which could increase the time for drilling during the surgery or even make it necessary to exchange the instrument or to change to another OP technique.

The Combination Reamer Drill is part of the Combination Reamer Assembly, as well as a single instrument, both being part of the Omega 3 instrument set.

Potential Hazards

Potential hazards associated with the use of the instrument are:

- Exchange of instrumentation might become necessary
- Change of surgery method (opening procedure or other OP technique) might become necessary
- High friction of the blunt drill tip might lead to heat generation during drilling
- Surgery time might be extended by change of instrument or surgery method
- The drill might break or might not be able to penetrate the bone, but additional equipment might not be available

Risk Mitigation

A functional check of instruments should be executed before using instruments in a surgery.

The Osteosynthesis Reprocessing Guide "Instructions for Cleaning, Sterilization, Inspection and Maintenance" (ref L24002000) includes an instruction for the functional check of reamers in appendix 3. This check also points out to check for blunt and dull cutting flutes.

It is not likely, though, that the non-conformance of the Drill can be detected by standard visual inspection of the hospital staff without the knowledge of the non-conformance and its visual appearance.

A factor that obscures hazard awareness can be softer bone density, e.g. elderly patients, osteoporotic bone. Factors that heighten hazard awareness are verification of the device prior to each clinical use (compare IFU) and no penetration through cortex while drilling to be noticed by Health Care Professionals during surgery.

Actions Needed

Our records indicate that you have received the above referenced product(s) and we are requesting that you assist us in this Field Corrective Action by:

- Passing this Field Safety Notice to all those who need to be aware of it within your organization.
- If you have further distributed this product, please forward this letter and the attached Business Reply Form (**BRF**) to all affected locations. Please indicate each location on the BRF.
- Immediately check all stock areas or operating room storage and quarantine any affected product(s) found.
- Mark product as "PFA #2012-014 RECALLED PRODUCT".
- Please indicate on the BRF the quantity of affected Combo Reamer Drills you are returning and fill in the form completely.
- Sign the BRF (**even if you do not have any affected product**).

Note: *Your signature on the BRF indicates that you have received and understand this notification and are returning all affected product(s) from your facility.*

Return the Business Reply Form as fax within 5 business days to Stryker Osteosynthesis, Regulatory Department, to acknowledge your receipt and understanding of this information.

(need fax number*)

- Upon receipt of the BRF, Stryker will contact you to coordinate the return of all affected product that you have on hand.
- Send back all affected product using the pre-paid shipper provided to you by Stryker.

We sincerely regret any inconvenience caused to you by this action, however we know that you share our desire to ensure the highest quality standards in our products and reduce risks to patients. We would like to thank you for your co-operation in this matter. Should you require any further information or have any queries on the matter please do not hesitate to contact the undersigned.

Yours faithfully,

Name

Position

(address)

phone: xxxx-xxxx

fax: xxxx-xxxxxx

email: XXX.XXX@stryker.com

Enclosures:

Distribution List

Customer Response on Receipt

Customer Response on Return

CUSTOMER RESPONSE ON RECEIPT

We have received your letter dated March 19th, 2012 Ref. Voluntary Recall # 2012-0014, concerning the Combo Reamer Drill and Assembly ref. 704005, 704005-10 and 704006 with lots listed in the above given letter and will return all affected products available at our location to:

Stryker Trauma SA
Andreas Seiss
Ref. PFA #2012-014
2545 Selzach
Switzerland

Please return this page after completion to **forename Name** by email, fax or letter to:

Name
Position
(address)
phone: xxxx-xxxx
fax: xxxx-xxxxxx
email: XXX.XXX@stryker.com

Hospital / Customer Name: _____

Date / Printed Name / Signature: _____

CUSTOMER RESPONSE FORM

Please complete this form even if you do not have any product to return. This will preclude the need for future notices.

Stryker RA Reference Number	2012-014	
Product Description	COMBO REAMER DRILL and COMBO REAMER ASSEMBLY	
Product Code/Cat No	From: 704005-10; 704005; 704006; 990263	To: n/a
Lot/Serial Numbers	See attachment. PFA 2012-014 Trace affected lots	

Please check your inventory for affected product and return completed form to our Quality Department as soon as possible. Please note only the product codes/catalogue numbers specified are affected by this action.

Product Disposition (Completed by Customer)

Product Code/Cat No.	Lot/ Serial No	Qty to be returned	Qty /Used Implanted	Qty Disposed /or destroyed	Qty not located	Upgraded

Customer Details

Response requirements (please complete/delete appropriate section)

I have checked inventory and can confirm that we do not have any affected product at this location.
I have checked inventory and completed the product disposition table. Please arrange for collection of product.
I have completed the upgrade/maintenance of all the product listed above in accordance with the Product Field Action.
Please have Stryker service contact our maintenance department to arrange upgrade of the above listed product.
Please sign and return this form to acknowledge receipt of product notice.

Name of Hospital/ Organisation	Address
Contact Name	
Contact Title	
Contact Signature	
Contact Phone No.	Date

Completion Instructions

1. Complete and fax back this form to Stryker, Andreas Seiss, Fax: +41 32 641 66 60
2. A Stryker Representative will call you to arrange collection of product/upgrade if necessary.
3. Please ensure that the outer package is labelled with Stryker RA Reference number PFA 2012-014
4. Ensure that forms are secured in a document wallet on the outer of the package.
5. Please ensure that where appropriate a decontamination certificate is returned with product.