

«Hospital\_Name»  
 «Users\_Name»- «Department»  
 «Customer\_Address»  
 «Zip\_Code» «City» - «Country\_name»

**Reference: 91107242-FA**  
**Additional Recommendation**

xx December 2015

## Urgent Update Field Safety Notice Chariot™ Guiding Sheath

Dear «Users\_Name»,

In the previous notification sent on **DATE**, Boston Scientific advised that it is recalling its Chariot™ Guiding Sheath. To date, Boston Scientific has received fourteen complaints for shaft separation, four of which involved separation of the distal shaft. These events occurred during device preparation or use.

Although our records indicate you have already responded to BSC’s initial field action notification, we are contacting you to provide additional guidance and request acknowledgment of this communication:

**Physicians are encouraged to contact all patients who have undergone procedures involving Chariot to confirm their post-procedure status, as device shaft separation and embolized fragments may not have been recognized at the time of the procedure. To date, no permanent impairments or patient deaths have been reported.**

The most severe outcome of this failure is embolism of device fragments, which could lead to obstruction of blood flow or additional intervention to remove a device fragment. Obstruction of blood flow can result in injuries such as stroke, kidney damage or damage to the intestines or limbs.

Our records indicate that your facility received some of the concerned product. **Table below provides a complete list of all affected products**, including Product Description, Material Number (UPN) and Lot/Batch numbers and expiry date. Please note that **only the material listed below is affected. No other Boston Scientific product is involved by this Field Safety Notice.**

| Product Description     | Material Number (UPN) | Batch                                 | Batch Expiration Date Range      |
|-------------------------|-----------------------|---------------------------------------|----------------------------------|
| Chariot™ Guiding Sheath | H74939277645110       | See Attached Affected Product Listing | 31 March 2016 - 30 November 2018 |
|                         | H74939277690210       |                                       |                                  |
|                         | H74939277690220       |                                       |                                  |
|                         | H74939277845210       |                                       |                                  |
|                         | H74939277745210       |                                       |                                  |
|                         | H74939277645210       |                                       |                                  |
|                         | H74939277745110       |                                       |                                  |
|                         | H74939277665110       |                                       |                                  |
|                         | H74939277690110       |                                       |                                  |
|                         | H74939277765110       |                                       |                                  |
|                         | H74939277545110       |                                       |                                  |
|                         | H74939277690120       |                                       |                                  |
|                         | H74939277845110       |                                       |                                  |
|                         | H74939277790110       |                                       |                                  |
|                         | H74939277865110       |                                       |                                  |
| H74939277545210         |                       |                                       |                                  |
| H74939277790220         |                       |                                       |                                  |
| H74939277665120         |                       |                                       |                                  |

|  |                 |  |  |
|--|-----------------|--|--|
|  | H74939277645220 |  |  |
|  | H74939277645120 |  |  |
|  | H74939277745120 |  |  |
|  | H74939277790210 |  |  |
|  | H74939277790120 |  |  |
|  | H74939277890110 |  |  |
|  | H74939277765120 |  |  |
|  | H74939277865120 |  |  |
|  | H74939277890120 |  |  |
|  | H74939277845120 |  |  |
|  | H74939277745220 |  |  |

**INSTRUCTIONS:**

- 1- Please read this notice and the instructions attached to this letter.
- 2- **Please complete the attached Acknowledgement Form, even if you have already responded to the first recall notification and returned any remaining recalled units.**
- 3- **When completed, please return the Acknowledgement Form to your Boston Scientific office** to the attention of «Customer\_Service\_Fax\_Number» on or before **DATE**.
- 4- Please pass on this notice to any health professional of your organization that need to be aware and to any organization where the potentially affected devices have been transferred (If appropriate). Please provide Boston Scientific with details of any affected devices that have been transferred to other organizations (if appropriate).

Your Competent Authority is being notified of this Field Safety Notice.

We regret any inconvenience that this action may cause, and we appreciate your understanding as we take action to ensure patient safety and customer satisfaction.

If you have any questions or would like assistance with this Field Safety Notice, please contact your local Sales Representative.

Yours sincerely,



Marie Pierre Barlangua  
 Quality Department  
 Boston Scientific International S.A.

Attachments: - Acknowledgement Form  
 - Full affected Product listing