

Date: 30-01-2020

## <u>Urgent Field Safety Notice</u> <u>Needle guide bushings for stereotactic breast biopsy</u>

For Attention of\*:

Director of Breast Imaging Director of Radiology Director of Biomedical Engineering

This letter is distributed by Siemens Healthineers on behalf of the Turon Medtech AB informing affected customers who are operating Siemens Healthineers Mammography systems with a biopsy option using TURON plastic bushings.

Siemens Healthineers Mammography systems are not causing or contributing to the below described problem.

Contact details of local representative (name, e-mail, telephone, address etc.)\*

Turon MedTech AB Kardanvagen 21 SE-43232 Varberg Sweden +46 (0)340 84060

bushing@turonmedtech.com



## Urgent Field Safety Notice (FSN) Needle guide bushings for stereotactic breast biopsy may fail

## 1. Information on Affected Devices\*

## Device Type(s)\*

Sterile needle guide bushings for one-time use. These bushings are delivered sterile in pairs, i.e. one package includes two (2) bushings, according to picture 1. When using the stereotactic breast biopsy device, these bushings are used to guide the biopsy needle through the needle holder according to picture 2.





Picture 1

Picture 2

Commercial name(s) CYTOGUIDE Needle guide bushes: GA12, GA14, GA16, GA18, GA20, GA20 OPEN & GA22. 1 3. Unique Device Identifier(s) (UDI-DI) N/A 1 4. Primary clinical purpose of device(s)\* Needle guide bushings 5. Device Model/Catalogue/part number(s)\* 040301, 040302, 040307, 040308, 040309, 040311 & 040312 1 6. Software version 1 7. Affected serial or lot number range All bushings with these article numbers 8. Associated devices N/A



	2 Reason for Field Safety Corrective Action (FSCA)*							
2	Description of the product problem*							
	Some bushings have a material defect, which makes them brittle. The degree of thi							
	material defect varies. However, some of them, may break during normal usage in the							
	field. This has happened and has consequently been reported.							
2	2. Hazard giving rise to the FSCA*							
	When a bushing breaks, parts of it may fall on the breast, i.e. around the needle's entry							
	into the breast. This may require the biopsy operator to clean the breast, remove the							
	needle and replace the bushing. This could lead to extended surgery time and a potentially							
	stressful situation for both patient and operator. No injuries have been reported due to this							
	issue.							
2	Probability of problem arising							
-	N/A							



	3. Type of Action to mitigate the risk*								
3.	1. Action To Be Taken by the User*								
		☐ Identify Device	☐ Quara	antine Device	□ Return D	evice	□ Destroy Device     □		
		☐ On-site device modification/inspection							
		☐ Follow patient management recommendations							
		$\hfill\Box$ Take note of amendment/reinforcement of Instructions For Use (IFU)							
		☐ Other	er 🗆 None						
	If you have any of these bushings remaining, we strongly advise you, to stop using them. We will immediately and free of charge send you replacement bushings in stainless steel. For replacement please send an email to <a href="mailto:bushing@turonmedtech.com">bushing@turonmedtech.com</a> and you will get immediate respond with replacement instructions.						ss steel. For		
		Note that these stainles with the bushings.	ss-steel bu	shings will be delivered	nonsterile. A s	sterilization	n instruction will come		
3.	2.	By when should the action be complete	I	2020-04-30					
3.	Is customer Reply Required? *  (If yes, form attached specifying deadline for return)			See	3.1 & 3.2				
3.		4. Action Being Taken by the Manufacturer							
		<ul><li>☐ Software upgrade</li><li>☐ Other</li></ul>		]IFU or labelling char ]None	nge				
	As	As an immediate action we have stopped delivery of these bushings until the issue is mitigated.							
3	5.	,		2020-05-31					
		action be complete							
3.	6.	/lay user?			•	No			
3	7.			ovided additional in					
			y or non-	professional user in	ntormation le	etter/she	et?		
		N/A							



	4. General Information*						
4.	1. FSN Type*	New					
4.	For updated FSN, reference number and date of previous FSN	N/A					
4.	3. For Updated FSN, key new inform N/A	nation as follows:					
4.	4. Further advice or information already expected in follow-up FSN? *	'					
4	If follow-up FSN expected, what is the further advice expected to relate to:  N/A						
4	Anticipated timescale for follow- up FSN	N/A					
4.	7. The Competent (Regulatory) Authority of your country has been informed about this communication to customers. * Work in process regarding information to authorities						
4.	8. List of attachments/appendices:	N/A					
4.	9. Name/Signature	Göran Ekström and Martin Gröndahl Managing Director Business Developer					

Transmission of this Field Safety Notice
This notice needs to be passed on all those who need to be aware within your organisation or to any organisation where the potentially affected devices have been transferred. (As appropriate)
Please transfer this notice to other organisations on which this action has an impact. (As appropriate)
Please maintain awareness on this notice and resulting action for an appropriate period to ensure effectiveness of the corrective action.
Please report all device-related incidents to the manufacturer, distributor or local representative, and the national Competent Authority if appropriate, as this provides important feedback*

Note: Fields indicated by \* are considered necessary for all FSNs. Others are optional.