

Field Safety Notice

**Philips Azurion R2.0.x System
Inadvertent change of Patient Type when the study starts**

2022-Feb-08

This document contains important information for the continued safe and proper use of your equipment

Please review the following information with all members of your staff who need to be aware of the contents of this communication. It is important to understand the implications of this communication.

Please retain a copy with the equipment Instruction for Use.

Dear Customer,

A problem has been identified in the Philips Azurion R2.0.x system that could pose a risk for patients. This Field Safety Notice is intended to inform you about:

1. What is the problem and under what circumstances it can occur

In the Azurion system, the user can add a new study to a patient by selecting the option “Add Study”. The Add Study dialogue box is then displayed where the Patient Type is selected to perform the study. Due to a software defect, when the study is initiated by pressing “Start Procedure”, the Patient Type changes inadvertently to a Patient Type different than the one selected as shown in the following Table:

Patient type selected on the “Add study” dialogue box	Patient type when the study starts
Auto (Normal Adult)	Neonate
Neonate	Infant
Infant	Child
Child	Small Adult
Small Adult	Normal Adult
Normal Adult	Large Adult
Large Adult	Very Large Adult
Very Large Adult	Unknown (default)

Table 1: Differences between the Patient Type selected and the Patient Type when the study starts

Philips has received 9 (nine) customer complaints related to this problem.

2. What are the hazard/harm associated with this issue

A change in the patient type could lead to Image Quality Degradation (in case that the radiation dose is too low) or additional X-ray dose for the patient (when the radiation is higher than the one required). No harm is expected from the additional radiation dose.

To date, Philips has not received any reports of harm associated with this problem.

3. What are the affected products and how to identify them

The Philips Azurion 7 M20 systems (product code 722079) with a software R2.0.x, are affected.

The system product name and model number can be found in the System Identification Label located on the system stand (Fig. 1).

The software version of the Philips Azurion system is displayed during the start-up of the system (Fig. 2).





Fig. 1: System identification



Software Version

Fig. 2: Start-up screen

Philips is sending this notification directly to customers that have affected systems.

4. What actions should be taken by the customer / user in order to prevent risks for patients or users

- After pressing the “Start Procedure”, always edit the “Study details” and change the Patient Type before starting the Study (Fig. 3).




Fig. 3: Editing the Patient Type manually.

- Place this Field Safety Notice with the documentation of the system until Philips has installed a software update in your system.
- Circulate this notice to all users so they are aware of the product issue.

- Return the attached reply form to Philips to confirm that the users of the system have reviewed and understood this Field Safety Notice letter.

5. What are the actions planned by Philips IGT Systems to correct this problem

This problem will be resolved by a software update, which will be available by end of February 2022. You will be contacted by your local Philips representative to schedule the software update for your system.

Please be assured that maintaining a high level of safety and quality is our highest priority. If you need any further information, please contact your local Philips representative (reference to FCO72200508).

Sincerely,



Rajesh Kathuria
Head of Quality – IGT-Systems



Philips' proprietary information. Unauthorized use is prohibited.

FIELD SAFETY NOTICE RESPONSE FORM

Reference: 2021-IGT-BST-034

Instructions: Please complete and return this form to Philips promptly and no later than 30 days from receipt. Completing this form confirms receipt of the Field Safety Notice, understanding of the issue, and required actions to be taken.

Customer/Consignee/Facility Name: _____

Street Address: _____

City/State/ZIP/Country: _____

Customer Actions:

- After pressing the "Start Procedure", always edit the "Study details" and change the Patient Type before starting the Study.
- Circulate this letter to all users so they are aware of the product issue.
- Place this Field Safety Notice with the documentation of the system until the Philips has installed a software update in your system.

We acknowledge receipt and understanding of the accompanying Field Safety Notice and confirm that the information from this letter has been properly distributed to all users that handle the Azurion R2.0.x system.

Name of person completing this response form:

Signature: _____

Printed Name: _____

Title: _____

Telephone Number: _____

Email Address: _____

Date
(DD/MM/YYYY): _____