Urgent Field Safety Notice

Hugo[™] Robotic-Assisted Surgery (RAS) System ARM CART ASSEMBLY MRASC0002

Notification

March 2022

Medtronic Reference: FA1228

Dear Risk Manager, Healthcare Professional, and OR Materials Manager,

The purpose of this letter is to advise you that Medtronic is conducting a voluntary Urgent Field Safety Notice for the Hugo[™] robotic-assisted surgery (RAS) system. This field action affects the part number listed below:

ARM CART ASSEMBLY MRASC0002

Issue Description:

This Urgent Field Safety Notice is being taken following our investigation of three reports of a system error during preoperative calibration self-tests of the Hugo robotic arm cart assembly. Below we will explain this system error and the steps that should be taken to address it.

Calibration self-tests are performed by internal software during preoperative setup. These self-tests verify proper functioning of the robotic arm cart assembly and signal a non-recoverable error¹ if at least one of the self-tests fail.

The system will display a system notification of the failure giving the user the option to either recalibrate the arm cart assembly or ignore the arm and continue. If the user chooses the recalibrate option, the robotic arm cart assembly will be prevented from entering teleoperation even if the calibration is successful. This may cause procedural delays when the user subsequently attempts to enter teleoperation.

¹ A non-recoverable error means an error that can only be resolved by power cycling (i.e. turning off power to a component and then turning it back on).

Risk to Health:

There have been no patient injuries reported as a result of this system error. There is a potential for procedural delay and/or harm for unspecified tissue injury in a worst-case scenario, if this system error occurs and is not resolved during set up. Because this system error can be resolved preoperatively, the Hugo system may be safely used.

How to Address this System Error:

This system error can be addressed by following the Arm Cart Calibration Guide listed in Attachment #1 CE Arm Cart Calibration Guide.

Actions to be taken by the Customer:

- Notify all personnel in all care environments in which the Hugo RAS system is used about this urgent field safety notice.
- Provide all users with the applicable version of attached Arm Cart Calibration Guide.

Actions being taken by Medtronic:

- Medtronic is providing customers with an Arm Cart Calibration Guide.
- Medtronic is developing a software update that is expected to resolve this system error.
- Our Medtronic Technical Support/Field Service Department will assist customers with installing the software update after it is released.

Additional Information:

We regret any inconvenience that this issue may have caused. We are committed to patient safety and appreciate your prompt attention to this matter. If you have any questions regarding this communication, please contact your Medtronic representative.

Sincerely,

Local / BU Manager

Enclosure: Attachment 1 Arm Cart Calibration Guide

Attachment 1

Arm Cart Calibration Guide

This guide includes updated instructions to (1) determine if there is an arm cart calibration error and (2) recover from an arm calibration error. After completing arm calibration, the **Messages** log should always be viewed from the Surgery screen to confirm there are no arm calibration errors present. In the event of an arm calibration error, restart the arm cart by unplugging and reconnecting the arm cart data cable.

1. If any arms encounter a problem calibrating, the System Checks screen will show the particular arm with the error and provide options to either re-calibrate the arm or ignore the arm and continue.



If an arm has failed calibration, <u>do not</u> select the **Retry** or **Ignore & Continue** button. Instead, restart the arm by performing the following steps:

a. Unplug the arm cart data cable from the arm with the error. The arm will shut down and the system will display a message that the arm is no longer connected.



b. Reconnect the arm cart data cable. When the arm completes its startup, the arm cart LEDs will be green and the system will detect the connected arm and display the following message:

"Arm [ARM #]: New arm detected. Make sure arm is not over patient, and no instrument or port is attached. Touch CALIBRATE when ready."

Arm Cart Calibration Guide

DXXXX	ANVISETUP CALDE	
2		-
	The part of the second	10 10

Press Calibrate.

- c. If the arm fails calibration again, shut down the arm by unplugging the arm cart data cable and remove the arm from service.
- 2. Press the "**Messages**" button located on the menu located at the right of the OR team interactive display. The messages for this procedure are displayed in reverse chronological order (the most recent will be displayed first).

9000		Transformer 1	-
1	1 Aller		a
10			-
		The second second second	
V.		the second	
ALX.			
	Section Mensage Section intersection of space terms on our man architect land.	1221	
	Review Menager, Review research with space Review review state effective Rev. 1 Review Review Review Review Review	Received in the surgering we have been been as a second se	-
		(International Contraction Con	
			110

3. If either of the following errors appear in the list of messages, restart the arm according to the instructions in Step 1. If the error appears again, shut down the arm by unplugging the arm cart data cable and remove the arm from service.

"Arm[ARM#]: WARNING: Arm error. Withdraw instrument, unplug and reconnect arm. If error reoccurs, remove arm from use; contact Medtronic support." "Arm [ARM#]: WARNING: Arm error. If instrument inserted, use mechanical releases to withdraw. If no instrument, unplug and replug arm."

4. Continue to Arm Setup.

2

©2021 Medtronic. All Rights Reserved Covidien IIc. 15 Hampshire Street, Mansfield, MA 02048 USA Medtronic B.V., Earl Bakkenstraat 10, 6422 PJ Heerlen, The Netherlands Medtronic, and Medtronic logo are trademarks of Medtronic. All other brands are trademarks of a Medtronic company. **Third Party brands are trademarks of their respective owners. 2022-03



Medtronic

Hugo[™]RAS System