

Field Safety Notice, Medical Device Correction #148655

RayStation version 4.5 to 2024B including some service packs To determine if your version is affected, see build numbers listed in PRODUCT NAME AND VERSION below January 17, 2025 RSL-P-RS FSN Class III 148655

ISSUE

This notice concerns an issue found with the handling of the density uncertainty in *Robust optimization* and *Plan evaluation* for proton and light ion plans of RayStation version 4.5 to 2024B including some service packs.

To the best of our knowledge, the issue has not caused any patient mistreatment or other incidents. However, the user must be aware of the following information to avoid misleading robust evaluation results during treatment planning.

INTENDED AUDIENCE

This notice is directed to all users of RayStation version 4.5 to 2024B, who use *Compute perturbed dose* or *Robust evaluation* for proton or light ion treatment plans in the *Plan evaluation* module.

PRODUCT NAME AND VERSION

The products affected by this notice are sold under the trade names RayStation version 4.5 to 2024B including some service packs. To determine if the version you are using is affected, open the About RayStation dialog in the RayStation application and check if the build number reported there is "4.5.1.14-5.0.2.35", "5.0.3.17", "6.0.0.24", "6.1.1.2", "6.2.0.7", "6.3.0.6", "7.0.0.19", "8.0.0.61", "8.0.1.10", "8.1.0.47", "8.1.1.8", "8.1.2.5", "9.0.0.113", "9.0.1.142", "9.1.0.933", "9.2.0.483", "10.0.0.1154", "10.0.1.52", "10.0.2.10", "10.1.0.613", "10.1.1.54", "11.0.0.951", "11.0.1.29", "11.0.3.116", "11.0.4.15", "12.0.0.932", "12.1.0.1221", "12.0.3.68", "12.0.4.12", "12.3.0.119", "13.0.0.1547", "13.1.0.144", "13.1.1.89", "14.0.0.3338", "15.0.0.430", "15.1.0.852", or "16.0.0.847". If so, this notice applies to your version.

The single registration number (SRN) of the manufacturer: SE-MF-000001908

Product name	Build number	UDI-DI
RayStation 4.5.1 to RayStation 5 Service Pack 2	4.5.1.14-	N/A
	5.0.2.35	
RayStation 5 Service Pack 3	5.0.3.17	0735000201002020170502
RayStation 6	6.0.0.24	0735000201001320161214
RayStation 6 Service Pack 1	6.1.1.2	0735000201008220170529
RayStation 6 Service Pack 2	6.2.0.7	0735000201007520170630
RayStation 6 Service Pack 3	6.3.0.6	0735000201024220190923



Product name	Build number	UDI-DI
RayStation 7	7.0.0.19	0735000201006820171130
RayStation 8A	8.0.0.61	0735000201011220180608
RayStation 8A Service Pack 1	8.0.1.10	0735000201013620180928
RayStation 8B	8.1.0.47	0735000201012920181209
RayStation 8B Service Pack 1	8.1.1.8	0735000201020420190214
RayStation 8B Service Pack 2	8.1.2.5	0735000201023520190524
RayStation 9A	9.0.0.113	0735000201017420190612
RayStation 9A Service Pack 1	9.0.1.142	0735000201048820220420
RayStation 9B	9.1.0.933	0735000201026620191220
RayStation 9B Service Pack 1	9.2.0.483	0735000201029720200310
RayStation 10A	10.0.0.1154	0735000201030320200526
RayStation 10A Service Pack 1	10.0.1.52	0735000201036520200526
RayStation 10A Service Pack 2	10.0.2.10	0735000201065520220608
RayStation 10B	10.1.0.613	0735000201031020201216
RayStation 10B Service Pack 1	10.1.1.54	0735000201047120220128
RayStation 11A	11.0.0.951	0735000201038920210518
RayStation 11A Service Pack 1	11.0.1.29	0735000201043320210610
RayStation 11A Service Pack 2	11.0.3.116	0735000201044020210916
RayStation 11A Service Pack 3	11.0.4.15	0735000201063120220616
RayStation 11B	12.0.0.932	0735000201042620211208
RayStation 11B Service Pack 1	12.1.0.1221	0735000201049520220312
RayStation 11B Service Pack 2	12.0.3.68	0735000201050120220422
RayStation 11B Service Pack 3	12.0.4.12	0735000201060020220620
RayStation 11B Service Pack Toshiba 1	12.3.0.119	0735000201057020221222
RayStation 12A	13.0.0.1547	0735000201054920220616
RayStation 12A Service Pack 1	13.1.0.144	0735000201067920221007
RayStation 12A Service Pack 2	13.1.1.89	0735000201073020230913
RayStation 2023B	14.0.0.3338	0735000201055620230630
RayStation 2024A	15.0.0.430	0735000201072320231213
RayStation 2024A SP1	15.1.0.852	0735000201076120240508
RayStation 2024B	16.0.0.847	0735000201077820240625

DESCRIPTION

This notice is to inform about an inconsistency in the use of *Density uncertainty* in the RayStation functions *Robust optimization*, *Robust evaluation* and *Compute perturbed dose* for proton and light ion treatment plans when a HU-to-mass density CT calibration curve is used.

In *Robust evaluation* and *Compute perturbed dose*, in cases when a HU-to-mass density CT calibration curve is used, the density uncertainty is added to the nominal mass densities of the patient *prior to* the elemental composition assignment of the voxels. This handling is in line with the description in the UI, which states that *"The density uncertainty is modelled by scaling the mass density of the patient"*. However, since the stopping power is not a linear function of the mass densities found in a patient, a scaling of the mass densities prior to the elemental composition assignment of the voxels will not lead to a corresponding scaling of stopping power and water equivalent (WE) range. The result is that the relative change in stopping power and WE range will be less than the given change in mass density. For example, for a



prostate case with a distal depth of 240 mm, a density change of -3.5% will lead to an increased range of about 6 mm. However, an increase of 6 mm in range corresponds to only -2.5% change in stopping power, and +2.5% in range. If the change of -3.5% is applied to the stopping power instead of the mass density, the resulting change in range would be 8.4 mm, which is 2.4 mm more than the 6 mm resulting from the same change in mass density. While the handling of scaling the patient's mass densities is not incorrect, a user may assume that a change of the mass density in the RayStation UI would lead to a corresponding change in stopping power and WE range.

In *Robust optimization*, on the other hand, the stopping power and WE range of the scenario doses do scale according to the *Density uncertainty* given in the *Robustness settings* dialog. This is explained by the fact that the mass densities used in the dose calculation of the robust optimization are scaled *after* the elemental composition assignment of the voxels. This behavior is inconsistent with the behavior in *Robust evaluation* and *Compute perturbed dose* as described above, but may be more in line with what the user expects (i,e, that the given uncertainty is related to stopping power and WE range, rather than mass density). For RayStation 10A and earlier versions, the density/stopping power uncertainty in the *Optimization Settings Robustness* dialog was correctly labeled as "Range uncertainty". However, from RayStation 10B an onwards, it was relabeled as "Density uncertainty" to harmonize with the labeling in *Plan evaluation*. But, considering the different handling of *Density uncertainty* in *Plan evaluation* as described above, the labeling of the uncertainty in *Robust optimization* as "Density uncertainty" could be misleading.

For plans that are based on a HU-to-SPR CT-calibration curve, the density uncertainty given in *Robust evaluation*, *Compute perturbed* dose and *Robust optimization* is used directly to scale stopping power and therefore WE range. This is in contrast to the description of the functions in the UI, which states that it is the mass density that is scaled (see above).

For patient volumes associated with a material override, only the mass density of those volumes is affected by the density uncertainty while the elemental composition remains unchanged. This means that the stopping power in volumes with a material override will scale according to the user-defined mass density uncertainty for all functions in RayStation and irrespective of type of CT calibration curve.

For a user who evaluates a plan based on a HU-to-mass density CT calibration curve, and who expects that the given uncertainty in density will lead to a corresponding change in stopping power and WE range, the detectability of the inconsistency is likely low since the difference for limited range plans is not that large. Furthermore, if the plan has been robustly optimized, it is more likely to pass a robust evaluation, since the density perturbation in evaluation will lead to smaller changes in dose than in the optimization (assuming that the same density uncertainty was used for robust optimization and evaluation).

RSL-P-RS FSN Class III 148655 EN Field Safety Notice, Medical Device Correction #148655



ACTIONS TO BE TAKEN BY THE USER

- Inspect your product and identify all installed units with the above software version number(s).
- Educate planning staff and all users on how the density uncertainty is used in RayStation as described in section DESCRIPTION, and about the workarounds suggested below.
- Confirm you have read and understood this notice by replying to the notification email.

For users of HU-to-mass density CT calibration curves

If a user wants to evaluate a plan with respect to relative stopping power/WE range error rather than mass density errors, there are two options:

Option 1. Use a HU-to-SPR CT calibration curve instead of a HU-to-mass density curve.

- For evaluation of an existing case, the evaluation can be done on an anonymized and exported copy of the patient and plan.
- Contact RaySearch Service if you need help with the creation of a HU-to-SPR curve from an existing HU-to-mass density curve.

Option 2. Evaluate the plan using a higher (effective) mass density uncertainty that gives similar relative stopping power and WE range change as the nominal value.

• The following values of Effective mass density errors that give similar result as an intended Stopping power error have been deduced from a limited set of patients:

Stopping power error (%)	Effective mass density error (%)	
-3.5	-4.7	
3.5	4.2	
-2.0	-3.0	
2.0	2.2	

- For other values of intended Stopping power error, interpolate the approximate Effective mass density value from the table above.
- The values are estimates based on a few patients and are expected to vary slightly depending on the mass densities along the beam path.
- Note that the values are not symmetrical around 0.

For users of HU-to-SPR CT calibration curves

Be aware that the density uncertainty given in *Robust evaluation*, *Compute perturbed* dose and *Robust optimization* is used directly to scale stopping power and therefore WE range.

SOLUTION

Starting from RayStation v2025, scheduled for market release in April 2025 (subject to market clearance in some markets), the impact of the mass density uncertainty in *Robust evaluation* and *Compute perturbed dose* when using a HU-to-mass density CT calibration curve will be changed to harmonize with the other use cases. This means that as of RayStation v2025, the impact of mass density uncertainty will be implemented such that the relative change in stopping power and WE range will follow the given change in



mass density for all RayStation functions and for both types of CT calibration. The description of the functions in the UI and the product documents will be updated to better describe the meaning and effect of the mass density uncertainty.

If customers wish to continue using versions of RayStation affected by this notice, all users must maintain awareness of this notice. Alternatively, customers can choose to upgrade to the new version once it becomes available for clinical use.

TRANSMISSION OF THIS NOTICE

This notice needs to be passed on to all those who need to be aware within your organization. Maintain awareness of this notice as long as any affected version is in use.

Thank you for your cooperation, and we apologize for any inconvenience.

For regulatory information, please contact <u>quality@raysearchlabs.com</u>.

RaySearch will notify the appropriate regulatory agencies about this Field Safety Notice.



CONFIRMATION OF RECEIPT

PLEASE CONFIRM THAT YOU HAVE RECEIVED THIS FSN

Reply to the same email address that sent you this notice, stating you have read and understood it.

Alternatively, you can email or phone your local support to acknowledge this notice.

If you want to attach a signed reply form to the email, please fill in the below. You can also fax this form to Fax: +1-631-828-2137 (US only).

From: _		 _ (name of institution)
Contact person: _		 _ (please print)
Telephone no: _		 _
Email: _		 _
I have read and und	derstood the notice.	
Comments (optiona	al):	

RSL-P-RS FSN Class III 148655 EN Field Safety Notice, Medical Device Correction #148655