

Urgent Field Safety Notice

ACHC25-07.C.OUS

Atellica CH Analyzer Atellica CI Analyzer

Title	Potential for Falsely Depressed Results with the Atellica CH UCFP Assay										
Date Issued	Aug-2025										
Products	<table><tr><th>Assay</th><th>Test Code</th><th>Siemens Material Number / Unique Device Identification</th><th>Lot Number</th></tr><tr><td>Atellica CH Urinary/Cerebrospinal Fluid Protein</td><td>UCFP</td><td>11097543 / 00630414279206</td><td>All lots</td></tr></table>	Assay	Test Code	Siemens Material Number / Unique Device Identification	Lot Number	Atellica CH Urinary/Cerebrospinal Fluid Protein	UCFP	11097543 / 00630414279206	All lots		
Assay	Test Code	Siemens Material Number / Unique Device Identification	Lot Number								
Atellica CH Urinary/Cerebrospinal Fluid Protein	UCFP	11097543 / 00630414279206	All lots								
Issue Description	<p>Siemens Healthineers has confirmed, through an internal investigation of customer complaints, the potential for falsely depressed patient, quality control (QC), and/or calibration results. The observations have been isolated to the initial replicate(s) of a freshly punctured Atellica CH UCFP reagent well that has been stored onboard the system. The issue is intermittent and will not occur in all packs or wells. The issue may be observed with all sample types (urine and cerebrospinal fluid) for any Atellica CH UCFP reagent lot on an Atellica CH or CI analyzer.</p> <p>All future lots are impacted until further notice. Siemens is working to determine root cause and restore the assay performance.</p> <p>See “Appendix” for Detailed Customer Instructions.</p>										
Impact to Results	<p>When this issue occurs, there is a potential for falsely depressed result(s). If QC or calibration is affected, an apparent delay in testing may occur. The maximum negative bias observed during the investigation was -19.0 mg/dL (-190 mg/L), which may occur across the measuring interval. Results of this test should always be interpreted in conjunction with the patient’s medical history, clinical presentation, and other findings.</p>										
Customer Actions	<ul style="list-style-type: none">• Moving forward, keep only one (1) Atellica CH UCFP reagent pack onboard the system at a time.• Unload any Atellica CH UCFP packs that are currently onboard the system.• Siemens is instructing customers to perform QC on each well. Follow the instructions provided below:<ul style="list-style-type: none">○ Enable QC on Pack Change By Assay Type for CH to allow for QC to be processed when switching between wells. (See “Appendix” for detailed instruction)<p>Note: This setting enables QC on Pack Change for all CH assays. All QC Levels for CH assays for which this is not required should be deselected in the QC Master List.</p> <p>If your laboratory is using the Atellica to monitor QC:</p> <ul style="list-style-type: none">○ Enable Patient QC Flagging to allow for impacted patient results to be identified after a QC failure. (See “Appendix” for detailed instruction) <p>Note: All impacted patient results will have a “QC Fail” flag. Ensure that a result with a flag of “QC Fail” is held for review so that it can be rerun after passing QC.</p>										

-
- Upon QC failure, manually reorder QC.
 - Verify that QC results are passing. Once acceptable QC has been obtained, repeat all UCFP testing for all patient results flagged with “QC Fail.”
 - If QC results are still unacceptable after 2 attempts, unload the reagent pack and replace with a fresh pack.
 - If you experience repeated QC issues on consecutive wells, follow your laboratory protocol for additional QC troubleshooting to evaluate potential alternative causes for QC failures.

If your laboratory uses the Atellica Data Manager or other middleware to monitor QC:

- After a failed QC, ensure any UCFP samples processed after the failed QC are held for review.
 - Repeat QC.
 - Verify QC results are passing and repeat any held UCFP testing
 - If QC results are still unacceptable after 2 attempts, unload the reagent pack and replace with a fresh pack.
 - If you experience repeated QC issues on consecutive wells, follow your laboratory protocol for additional QC troubleshooting to evaluate potential alternative causes for QC failures.
-
- As a result of these actions, track additional reagent consumption (number of tests) to report to Siemens Healthineers for future reimbursement/credit.
 - Please review this letter with your Medical Director to determine the appropriate course of action, including for any previously generated results, if applicable.
 - Please retain this letter with your laboratory records and forward this letter to those who may have received this product.

**Single Registration
Number (SRN)**

US-MF-000016560

Resolution

A follow-up communication will be provided when “Customer Actions” are no longer required.

We apologize for the inconvenience this situation may cause. If you have any questions, please contact your Siemens Healthineers Customer Care Center or your local Siemens Healthineers technical support representative.

Siemens Healthineers

Siemens Healthcare Diagnostics Inc.
511 Benedict Avenue, Tarrytown, NY 10591
siemens-healthineers.com

Appendix Customer Actions – Enable QC on Pack Change By Assay Type

Refer to Atellica Solutions and Atellica CI Analyzer Online Help Guide for more detailed information on these settings.

1. From the System Navigator icon under QC, select **QC Settings**.
2. Under QC Mode Settings, select **By Assay Type**.

The screenshot shows the 'QC Settings' window. On the left, 'QC settings' is selected. Under 'QC Mode Settings', 'By Assay Type' is chosen. The 'QC on Pack Change' dropdown is set to 'Disable'. The 'QC Required' dropdown is set to 'Disable'. The 'QC Results Review Mode Settings' section shows 'Hold Results by Analyzer' with 'CM00295' selected. The 'QC Schedule' section shows 'Warn prior to QC schedule if endpoint control is unavailable' and 'When to Warn' settings.

3. For CH, click the drop-down menu for **QC on Pack Change** and choose **Enable**.
4. Select **Save**.
5. Under QC settings, click on **QC Master List** and search for UCFP.
6. If pack change is not set to All, click **Setup** and select all QC levels for both sample types.
7. For all CH assays for which QC on Pack Change is not required, expand the QC list and deselect all levels of QC.

The screenshot shows the 'QC Master List' window. The 'Filter' section shows 'Assay: UCFP'. The table lists assays with columns for 'Tests', 'Specimen Type', 'Material Name', 'Lot', 'Expiration Date', 'Pack Change', 'QC with Cal', and 'QC Required'. The 'Pack Change' column is set to 'All'. The 'QC Required' column has 'Setup' buttons for each assay.

Tests	Specimen Type	Material Name	Lot	Expiration Date	Pack Change	QC with Cal	QC Required
UCFP	Multiple	UCFP URINE QC	97410	08/31/2026	All	Levels	Disabled
		UCFP URINE QC	97471	08/31/2026	1	Levels	Disabled
		UCFP URINE QC	97472	08/31/2026	2	Levels	Disabled
	CSF	UCFP CSF QC	56580	09/30/2026	Levels	Setup	Setup
		UCFP CSF QC	56581	09/30/2026	1	Levels	Setup
		UCFP CSF QC	56582	09/30/2026	2	Levels	Setup

8. Select **Save**.


Siemens Healthineers

Siemens Healthcare Diagnostics Inc.
511 Benedict Avenue, Tarrytown, NY 10591
siemens-healthineers.com


Customer Actions – Enable Patient QC Flagging, for labs using the Atellica to monitor QC

Refer to Atellica Solutions and Atellica CI Analyzer Online Help Guide for more detailed information on these settings.

1. From the System Navigator icon under QC, select **Patient QC Flagging**.
2. Select **UCFP** Urine and CSF specimen types, **Edit/View**, select **Automatic** and click **Save**.



3. Ensure Patient QC Flagging is set to **Automatic** for Urine and CSF sample types.



Atellica is a registered trademark of Siemens Healthcare Diagnostics Inc. © Siemens Healthcare Diagnostics Inc. 2024

Siemens Healthineers

Siemens Healthcare Diagnostics Inc.
511 Benedict Avenue, Tarrytown, NY 10591
siemens-healthineers.com