

Lugano, October 2016

At the kind attention of:  
To whom it may concern

---

## Urgent Field Safety Notice

Commercial name of the affected product: **FlexLab**  
FSCA-identifier: **FSCA-201610-01**

---

### Details on affected devices:

Power cords of the following FlexLab modules/components:

- Storage & Retrieval Module
- Centrifuge Module
- i2000 SR Interface Module
- Router

### Description of the problem and related corrective action:

Inpeco became aware of power cords whose socket might overheat.  
The risk of User injury is negligible.  
Inpeco Service or their representatives will visit the Customer site to replace the power cords.

### Advise on action to be taken by the User:

Complete and return the Field Correction Effectiveness Check form attached to this letter within 7 days.  
Please transfer this notice to whom it might concern.

Inpeco apologizes for the inconvenience this situation may cause.  
For any clarification you may need, do not hesitate to contact:

Giorgia Amabile - Quality Assurance & Regulatory Affairs Manager  
E-mail: [giorgia.amabile@inpeco.com](mailto:giorgia.amabile@inpeco.com)  
Phone: (+41) 91 9118 258



---

Giorgia Amabile, Quality Assurance & Regulatory Affairs Manager

---

### INPECO S.A.

Via San Gottardo, 10 - 6900 Lugano - Switzerland  
Partita IVA: CHE-114.538.298



**FIELD CORRECTION EFFECTIVENESS CHECK**  
**Power Cord Connection**

This response form is to confirm receipt of the enclosed Field Safety Notice dated October 2016 regarding Power Cord Connection.

Please fill in the form and send a scan copy to [Regulatory.Affairs@inpeco.com](mailto:Regulatory.Affairs@inpeco.com).

Name of person filling in the form:

---

Title:

---

Institution:

Automation Serial Number:

---

Street:

---

City:

State:

---

Phone:

Country:

---

---

**INPECO S.A.**

Via San Gottardo, 10 - 6900 Lugano - Switzerland  
Partita IVA: CHE-114.538.298

Lugano, October 2016

At the kind attention of:  
To whom it may concern

---

## Urgent Field Safety Notice

Commercial name of the affected product: **Accelerator a3600**  
FSCA-identifier: **FSCA-201610-02**

---

### Details on affected devices:

Power cords of the following Accelerator a3600 modules/components:

- Storage & Retrieval Module
- Centrifuge Module
- i2000 SR Interface Module

### Description of the problem and related corrective action:

Inpeco became aware of power cords whose socket might overheat.  
The risk of User injury is negligible.  
Inpeco Service or their representatives will visit the Customer site to replace the power cords.

### Advise on action to be taken by the User:

Please transfer this notice to whom it might concern.

Inpeco apologizes for the inconvenience this situation may cause.  
For any clarification you may need, do not hesitate to contact:

Giorgia Amabile - Quality Assurance & Regulatory Affairs Manager  
E-mail: [giorgia.amabile@inpeco.com](mailto:giorgia.amabile@inpeco.com)  
Phone: (+41) 91 9118 258



---

Giorgia Amabile, Quality Assurance & Regulatory Affairs Manager

---

### INPECO S.A.

Via San Gottardo, 10 - 6900 Lugano - Switzerland  
Partita IVA: CHE-114.538.298

Lugano, October 2016

At the kind attention of:  
To whom it may concern

---

## Urgent Field Safety Notice

Commercial name of the affected product: **Aptio Automation**  
FSCA-identifier: **FSCA-201610-03**

---

### Details on affected devices:

Power cords of the following Aptio Automation modules/components:

- Storage & Retrieval Module
- Centrifuge Module
- i2000 SR Interface Module
- Router

### Description of the problem and related corrective action:

Inpeco became aware of power cords whose socket might overheat.  
The risk of User injury is negligible.  
Inpeco Service or their representatives will visit the Customer site to replace the power cords.

### Advise on action to be taken by the User:

Complete and return the Field Correction Effectiveness Check form attached to this letter within 7 days.  
Please transfer this notice to whom it might concern.

Inpeco apologizes for the inconvenience this situation may cause.  
For any clarification you may need, do not hesitate to contact:

Giorgia Amabile - Quality Assurance & Regulatory Affairs Manager  
E-mail: [giorgia.amabile@inpeco.com](mailto:giorgia.amabile@inpeco.com)  
Phone: (+41) 91 9118 258



---

Giorgia Amabile, Quality Assurance & Regulatory Affairs Manager

---

### INPECO S.A.

Via San Gottardo, 10 - 6900 Lugano - Switzerland  
Partita IVA: CHE-114.538.298



**FIELD CORRECTION EFFECTIVENESS CHECK**  
**Power Cord Connection**

This response form is to confirm receipt of the enclosed Field Safety Notice dated October 2016 regarding Power Cord Connection.

Please fill in the form and send a scan copy to [Regulatory.Affairs@inpeco.com](mailto:Regulatory.Affairs@inpeco.com).

Name of person filling in the form:

---

Title:

---

Institution:

Automation Serial Number:

---

Street:

---

City:

State:

---

Phone:

Country:

---

---

**INPECO S.A.**

Via San Gottardo, 10 - 6900 Lugano - Switzerland  
Partita IVA: CHE-114.538.298