



To users of the HemoCue® Glucose 201 RT Microcuvettes single pack

Product information letter

Affected products:

HemoCue® Glucose 201 RT Microcuvettes (single pack)

Article number: 114701, 114703, 114704 Within lot number: 1207906 to 1304996

Identifier: 2013-07-29_GL_RT

Information regarding defect packaging material for single packed Microcuvettes
HemoCue has recently become aware of a production related problem, which has
affected some of the packaging material for single packed Glucose 201 RT
Microcuvettes from lot numbers mentioned above. The root cause of the problem has
been identified and the problem has been corrected in the manufacturing process.

We would like to inform you that HemoCue® Glucose 201 **RT** Analyzers used together with the affected Microcuvettes still perform according to the ISO 15197:2003 standard.

Transmission of the Product information letter

This notice must be passed on to all that need to be aware within your organisation. Please sign the Product Information Verification form below and return to HemoCue AB.

We apologize for any inconvenience this may cause you. If you have any questions regarding this issue, please send an e-mail to local representative or to cuvettes@hemocue.se.

Yours sincerely, HEMOCUE AB

Mats Lindfors

Director of Marketing and Legal Affairs

Eva Steinick

Ass. Dir. Quality & Regulatory

Management

Phone: +46 431 48 12 00 Fax: +46 431 48 12 25 E-mail: info@hemocue.se Org no: 556342-9272



Product information Verification form

Identifier: 2013-07-29_GL_RT

I hereby confirm that I have read and understood the information in this Product Information Letter concerning defect packaging material.

I confirm that this notice has been passed on to all that need to be aware within my organisation.

Date:	
Signature:	
Name in block letters:	
Institution:	
Full address:	

Please sign and return to:

e-mail: to local representative or <u>cuvettes@hemocue.se</u>

or

fax: +46 77 570 02 12