

**URGENT - FIELD SAFETY NOTICE**

Type of Action:			Recall		
Teleflex Reference:			003-2014		
Commercial Name	Product Code	Lot Numbers	Commercial Name	Product Code	Lot Numbers
BRONCHIAL DOUBLE LUMEN TUBE SET (LEFT), STERILE	116100260	Refer to Appendix 2	BRONCHIAL DOUBLE LUMEN TUBE SET (RIGHT), STERILE	116200-000390	Refer to Appendix 2
	116100280			116200-000410	
	116100350			115900-000065	
	116100370		115900-000080		
	116100390		BRONCHIAL ONE LUMEN TUBE - LEFT	115901-000065	
	116100410		BRONCHIAL ONE LUMEN TUBE - RIGHT	115901-000080	
	116100-000260		CARLENS BRONCHIAL DOUBLE LUMEN TUBE SET (LEFT), STERILE	116101370	
	116100-000280			116101390	
	116100-000350			116101410	
	116100-000370			116101-000350	
	116100-000390			116101-000370	
	116100-000410			116101-000390	
	16100-000350			116101-000410	
	BRONCHIAL DOUBLE LUMEN TUBE SET (RIGHT), STERILE		116200260	Refer to Appendix 2	
116200280		116400-000850			
116200350		116400-000950			
116200370		TRACHEOPART SET (RIGHT), STERILE	116401-000750		
116200390			116401-000850		
116200410			116401-000950		
116201350		WHITE BRONCHIAL DOUBLE LUMEN TUBE SET (RIGHT), STERILE	116201-000350		
116201410			116201-000370		
116200-000260			116201-000390		
116200-000280			116201-000410		
116200-000350		(BRONCHIAL DOUBLE LUMEN TUBE SET (LEFT), EXTRA LENGTH, STERILE)	116164-000390		
116200-000370					


Dear Customer,

**1. Details of affected devices**

Teleflex have initiated a voluntary Field Safety Corrective Action for the above listed products.

**2. Description of the problem**

Teleflex are recalling the products referenced above following receipt of customer complaints reporting that the Cobb connector detached from the main connector prior to use. This Cobb connector detachment should be readily identified by the user during set-up and prior to use of the device. If during use, Cobb connector separation occurs and presents as a leak in the breathing circuit and if it is unnoticed, then there is a remote probability that the patient may need to be re-intubated due to the risk of respiratory distress and hypoxia.



**3. FIELD SAFETY CORRECTIVE ACTION INSTRUCTIONS:**

**ADVICE ON ACTION TO BE TAKEN BY MEDICAL STAFF**

1. Clinical recommendation regarding action that should be taken by users and/or healthcare professionals in relation to devices which are currently in use in patients: "The clinical end-user is advised to remove the Cobb connector which are currently in use in patients and replace with an alternative connector."
2. We request that you check your inventory for product within the scope of this field action. Users should cease use and distribution of stock of the affected product batch and quarantine immediately.
3. If you do not have stock in scope of this field action as referred to in above table then mark the according checkbox on the Acknowledgement form (Appendix 1) and return the form to the fax number or e-Mail-address mentioned below.
4. If you have stock from the affected product as referred to in above table, mark the according checkbox on the Acknowledgement form (Appendix 1). Contact customer service by calling the phone number mentioned in Section 6 who will issue you with a return number. Write this return number into the respective field in the Acknowledgement form.
5. Complete 'Appendix 1' for all products in your possession and under control. Return this form immediately to Customer Service.
6. Teleflex (or your local dealer) will issue a credit note upon receipt of the returned affected product.

**INSTRUCTION FOR DISTRIBUTORS OF AFFECTED PRODUCT**

1. If you are a distributor, provide this field safety notice to all of your customers who have received product in scope of this Field Action. Your customer is then required to complete the acknowledgement form and return this to you.
2. As a Distributor you are required to confirm to Teleflex that you have completed the field activity outlined above. Upon completion of your actions, please forward the completed Acknowledgement Form to Customer Service.
3. Please be aware that all European Economic Area/Switzerland (EEA/CH) and Turkey Member State Competent Authorities in which Teleflex distribute directly will be notified by Teleflex.
4. If you are a distributor and/or have a reporting responsibility within or outside the EEA/CH/TK area, please notify your local Competent Authority of this action. Please forward the notification and all communication with your local competent authority to Teleflex.

**4. Teleflex**

Teleflex informs all customers, employees of Teleflex and distributors on this Field Action.

**5. Transmission of this Field Safety Notice**

This notice should be passed on to all persons who need to be aware within your organization or to any organization where the potentially affected devices have been transferred. Please consider end users, clinicians, risk managers, supply chain/distribution centres etc. in the circulation of this notice.

Maintain awareness of this notice until all required actions have been completed in your organisation

**6. Contact reference person**

Should you require any further information or support concerning this issue, please contact:

**Customer Service**

**Contact:** Shane Kenny  
**FAX:** +353 (0)1 4370773

**Telephone:** +353 (0)906460869  
**E-mail:** orders.intl@teleflex.com

Please be advised that all European Economic Area/Switzerland (EEA/CH) and Turkey Member State Competent Authorities to which Teleflex distribute directly will be notified by Teleflex.

Teleflex is committed to providing high quality, safe and effective products. We sincerely apologize for any inconvenience this action may cause your operations. If you have any other questions, feel free to contact your local sales representative or Customer Service.

*For and on behalf of Teleflex,*

*Karen Boylan*

---

**Karen Boylan**  
**VP Global RA/QA**

**Appendix 1**

**Customer No:** \_\_\_\_\_

**FIELD SAFETY CORRECTIVE ACTION**

Teleflex Ref. 003-2014

**Acknowledgement Form**

**URGENT ATTENTION REQUIRED**

**Return completed form immediately to:**

**FAX:** +353 (0)1 4370773

**E-mail:** orders.intl@teleflex.com

**Please check applicable box:**

<input type="checkbox"/> We confirm receipt of this FSN and completed the required actions contained therein. We confirm that our inventory does <b>NOT</b> include products affected by this Field Action.	<input type="checkbox"/> We confirm receipt of this FSN and completed the required actions contained therein. We confirm our inventory <b>DOES</b> include products affected by this Field Action. The use and further distribution of the affected products has been stopped. All products are on hold and the quantity stated below will be returned.
<div style="border: 1px solid red; padding: 5px; display: inline-block; margin: 0 auto;"> <b>Return Authorisation No</b> _____         </div>	

**Please CLEARLY print the below return information:**

<b>Name of Affected Products:</b>	BRONCHIAL DOUBLE LUMEN TUBE SET (LEFT), STERILE   BRONCHIAL DOUBLE LUMEN TUBE SET (RIGHT), STERILE   BRONCHIAL ONE LUMEN TUBE – LEFT   BRONCHIAL ONE LUMEN TUBE – RIGHT   CARLENS BRONCHIAL DOUBLE LUMEN TUBE SET (LEFT), STERILE   TRACHEOPART SET (LEFT), STERILE   TRACHEOPART SET (RIGHT), STERILE   WHITE BRONCHIAL DOUBLE LUMEN TUBE SET (RIGHT), STERILE		
<b>Product Number</b>	<b>(Size)</b>	<b>Lot Number</b>	<b>Quantity (Returning)</b>

**Return Instructions:**

- Please label product returns as “Field Action Returns”.
  - Include a copy of this form (including RAN Number) with product returns.
- Returns excluding ALL necessary documentation CANNOT be processed.

<b>Institution Name - (Hospital, Health Care Organisation, etc.)</b>	
<b>Institution Address:</b>	<b>Email Address:</b>
<b>Form completed by:</b>	<b>Phone Number:</b>
<b>Print Name :</b>	<b>Institution Stamp:</b>
<b>Signature :</b>	
<b>Date:</b>	

Appendix 2 - Page 1 of 3

Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number						
116100260	13GT24	116100390	13KT23	115900-000065	13FT06	115901-000080	14JT21	116100-000280	14DT19	116100-000350	14ET23	116100-000370	14BT15						
	13HT07		14AT12R		13GT24	13FT12	14DT20		14ET28		14BT16								
	13IT16		14BT09		13JT08	13FT17	14DT24		14FT04		14CT06								
	13KT23		14ET10		13KT12	13GT24	14ET04		14GT05		14CT11								
	14AT08		14ET11		13LT08	13HT07	14ET10		14GT10		14CT21								
	14DT19	13FT12R	14AT20		13HT12	14ET22	14HT09		14DT03										
	14ET10	13GT05	14DT19		13HT17	14ET23	14HT12		14DT10										
	14ET11	13HT07	14ET04		13IT05	14FT04	14HT17		14DT13										
	14FT04	13IT20	14GT10		13IT10	14FT05	14HT20		14DT24										
	14FT10	13JT25	14GT15		13IT20	14GT03	14IT05		14DT25										
	14GT03	13KT05	14IT11		13IT20R	14GT18	14IT17		14ET04										
	116100280	13GT24	116100410		13KT18	14JT09	13JT05R		14HT20		14JT04		14ET10						
		13KT05			14JT24	13LT04	14IT14		14JT09		14ET22								
		13KT23			14DT19	14BT15	14JT12		14JT12		14ET23								
14AT12		14ET04		14BT16	13FT06	14JT21	14ET28												
14ET23		14ET10		14CT16	13FT12	14JT24	14FE23J												
116100350	13GT24	116101370	14ET11	115900-000080	13KT12	116100-000260	14DE14J	116100-000350	13FT17	116100-000370	13FT06	116100-000390	14FT04						
	13HT07		14FT05		14AT04		13FT18		13FT12		14FT05								
	13IT16		14FT10		14BT04		13GT23		13FT18		14FT10								
	13JT08		13KT12		14BT15		13GT24		13GE27J		14GT03								
	13KT05		13LT04		14DT19		13HT07		13GE31J		14GT05								
	13KT18	13KT18	14ET04		13HT12		13GT05		14GT10										
	13KT23	13FT12R	14ET22		14GT21		13GT11		14GT15										
	13LT14	13GT05	14GT15		14HT09		13GT16		14GT18										
	14CT06	13JT11	14GT18		14HT12		13GT24		14GT23R										
	14DT10	13JT15	14IT14		14HT20		13GT29		14HT09										
	14DT19	14CT11	14JT09		14IT05		13HT07		14HT12										
	14ET23	13JT05	14JT18		14IT08		13HT12		14HT17										
	116100370	13GT11	116200280		13KT18		115901-000065		13FT06		116100-000350		14JT12	116100-000370	13JT11	116100-000370	13HT17	116100-000390	14HT23
		13GT24			14CT11				13IT05				14JT24		13IT05		14HT24		
13HT07		14FT05		13JT08	13GT16	13IT10		14IT05											
13IT16		14FT10		13KT12	13GT23	13KT12		14IT08											
13JT25		13FT12R		14CT11	13HT17	13KT18		14IT11											
13KT23		13GT11	14DT03	13IT10	13KT23	14IT17													
13LT04		13HT07	14DT24	13IT13	13LT04	14JT04													
13LT18		13KT23	14ET04	13IT16	13LT14	14JT12													
14CT11		14AT08	14FT04	13IT20	14AT08	14JT18													
14DT13		13KT23	14FT20	13IT20R	14AT16	14JT21													
14DT19		13LT14	14GT10	13JT08	14BT15	14JT24													
14DT24		14DT25	13GT16	13KT05	14BT21	13FT06													
14DT25		14ET23	13KT18	13KT18	14CT11	13FT12													
14ET10		13HT12	13LT08	13KT23	14CT16	13FT17													
14ET11	13JT08	14CT11	14AT08	14CT20	13FT18														
116100390	13FT12R	116200390	13KT18	115901-000080	14DT03	116100-000280	14AT12	116100-000350	14DT10	116100-000370	13LT14	116100-000390	13GT05						
	13HT07		14ET10		14DT24		14DT13		13LT18		13GT16								
	13IT16		14ET05		14GT15		14CT06		14AT08		13GT24								
	13JT11	14ET22	14HT12		14CT11		14DT19		13GT29										
	13JT15	13FT12R	14HT20		14CT16		14ET04		13HE35										
	13JT25	13GT05	14JT04		14DE14J		14ET05		13HT07										
13KT18	116201410	14ET04	14JT12	14DT10	13HT16														

Appendix 2 - Page 2 of 3

Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number
116100-000390	13HT17	116100-000390	14IT14	116100-000410	14FT13	116101-000370	14GT10	116101-000390	14JT12	116200-000260	13LT04	116200-000350	13KT23
	13IT10		14IT17		14FT16		14GT11	13FT06	14DT03		13LT04		
	13IT13		14JT04		14FT20		14GT15	13FT12	14ET04		13LT08		
	13JT05		14JT09		14GT05		14GT21	13GT05	14ET10		13LT11		
	13JT08		14JT12		14GT15		14HT17	13GT24	14ET22		14AT04		
	13JT11		14JT21		14GT18		14IT05	13GT29	14FT04		14AT08		
	13JT15		13FT06		14HT03		14IT11	13HT07	14GT11		14BT21		
	13JT20		13FT12		14HT09		14JT09	13HT12	14GT18		14CT06		
	13JT21		13FT18		14HT17		14JT14	13HT17	14GT21		14CT16		
	13JT25		13GT05		14HT24		13FT06	13IT16	14HT09		14CT20		
	13KT05	13GT11	14IT05	13FT12	13IT20R	14HT17	14CT21						
	13KT12	13GT16	14IT08	13GT05	13JT08	13FT06	14DT06						
	13KT18	13GT23	14IT17	13GT23	13JT11	13FT12	14DT24						
	13KT23	13GT29	14JT09	13GT29	13JT15	13GE29J	14ET04						
	13LT04	13HT07	14JT12	13HE35	13JT21	13HT12	14ET05						
	13LT14	13HT12	14JT21	13HT17	13KT12	13HT17	14ET22						
	14BT09	13HT17	116101-000350	14JT14	13IT05	13IT10	14FT04						
	14BT14	13IT05	116101-000350	13FT06	13IT16	13JT11	14FT10						
	14BT15	13IT10		13FT12	13IT20	13KT05	14FT13						
	14BT16	13IT16		13FT18	13IT20R	13KT18	14FT20						
	14BT21	13IT20		13GT05	13JT08	13LT11	14GT05						
	14CT06	13IT20R		13GT29	13JT21	14AT20	14GT15						
	14CT11	13JT08		13HT07	13KT12	14BT21	14HT09						
	14CT20	13JT15		13HT12	13KT15	14CT11	14HT20						
	14DT03	13KT05		13HT17	13KT18	14CT16	14DT10						
	14DT06	13KT12		13IT16	13LT04	14CT20	14DT24						
	14DT10	13KT18		13IT20R	13LT11	14DT13	14ET10						
	14DT13	13KT23	13JT08	14BT14	14DT19	14ET22							
	14DT15	13LT04	13JT21	14BT21	14ET05	14FT04							
	14DT24	13LT08	13KT12	14CT11	14ET10	14FT10							
	14EE21J	13LT18	13KT18	14CT21	14ET28	14GT03	14JT24						
	14ET04	14AT08	13LT04	14DT03	14FT13	14GT15	13FT17						
	14ET10	14AT16	116101-000370	14DT13	14FT16	14GT21	13GE28J						
	14ET22	14AT20	14AT08	14DT15	14GT15	14HT09	13GT05						
	14ET28	14BT15	14BT14	14DT19	14GT18	14IT05	13GT16						
	14FT04	14CT06	14BT15	14DT20	14DT25	14IT20	13HT12						
	14FT05	14CT11	14CT11	14DT25	14ET04	13GE28J	13IT05						
	14FT10	14CT16	14CT16	14ET04	14HT03	13GT05	13IT10						
	14FT13	14CT20	14DT10	14ET28	14HT17	13GT11	13IT16						
	14GT03	14CT20	14DT15	14FT04	14HT23	13GT23	13IT20R						
	14GT05	14DT06	14DT19	14FT16	14HT24	13GT29	13JT08						
	14GT15	14DT10	14DT24	14GT10	14JT09	13HT07	13JT15						
	14GT18	14DT13	14ET10	116164-000390	14BT21	13HT12	13KT05						
	14HT03R	14DT13	14ET11	14GT11	13FT12	13HT17	13KT12						
	14HT09	14DT24	14ET22	14GT21	13GE29J	13IT10	13KT23						
	14HT12	14EE21J	14ET22	14GT23R	13GT29	13IT13	13LT08						
	14HT17	14ET04	14FT04	14HT17	13HT12	13JT08	13LT14						
	14IT05	14ET05	14FT05	14HT23	13HT17	13JT20	14AT08						
	14IT11	14ET10	14FT10	14HT24	13IT10	13JT21	14AT12						
		14ET22	14FT13	14IT08	13JT05R	13KT05	14BT21						
		14FT10		14JT09	13JT21	13KT12	14CT06						

Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number	Product Code	Batch Number
116200-000370	14CT16	116200-000390	14FT04	116201-000350	13FT17	116201-000370	13KT23	116201-000390	14GT05	116400-000750	14GT03	116401-000750	13JT21R
	14DT03		14FT16		13GT05		13LT08		14GT18		14GT23		13KT23
	14DT13		14GT03		13GT24		13LT11		14GT21		14HT03		13KT23R
	14DT19		14GT15		13HT07		14AT08		14HT03		14HT23		14CT21
	14DT20		14GT21		13HT12		14CT06		14HT09		14IT05		14ET11
	14DT24		14HT03		13HT17		14CT11		14HT20		14IT17		14ET22
	14DT25		14HT17		13IT16		14CT20		14HT23		13FT18		14ET28
	14ET05		14HT23		13IT20		14DT19		14IT08		13GE31J		14FT16
	14ET23		14IT05		13JT20		14DT24		14IT14		13GT05		14GT15
	14ET28		14IT08		13JT21		14ET04		13IT20		13HT17		14GT23
	14FT04		14IT17		13JT25R		14ET10		13JT25R		13IT13		14IT17
	14FT13		14IT20		13KT05		14ET22		13KT05R		13JT15		14JT18
	14FT20		14JT12		13KT05R		14ET23		13KT12		13JT20		13IT05
	14GT03		14JT24		13KT12		14FT04		13KT15		13JT20R		13JT21R
	14GT18		13FT12		13KT23		14FT13		13KT18		13KT23R		13KT05
	14HT03		13GE30J		13LT08		14GT18		13LT11		13LT08		13LT08
	14HT09		13GT11		14CT06		14GT21		14AT08		14BT09		14CT16
	14HT12		13GT24		14CT11		14HT03		14CT11		14BT15		14DT19
	14HT17		13GT29		14CT20		14HT20		14CT16		14CT16		14ET10
	14IT08		13HT12		14DT03		14HT23		14CT21		14CT20		14ET22
14IT17	13HT17	14DT06	14IT05	14DT13	14DE15J	14FT16							
14JT21	13IT10	14DT19	14IT08	14DT19	14DT03	14GT05							
14JT24	13IT13	14ET10	14JT14	14ET04	14FE24J	14GT18							
116200-000390	13FT12	116200-000410	13IT20R	116201-000390	14ET23	116400-000750	14JT18	116400-000850	14ET22	116401-000850	14FT13	116401-000950	14HT03
	13FT18		13IT20R		14ET28		13FT06		14ET28		14GE28J		14HT09
	13GE28J		13JT05		14FT04		13GT11		14GT18		14GT18		13JT21R
	13GT16		13JT05R		14FT05		13HT07		14HT03		14GT21		14CT06
	13GT29		13JT20		14FT13		13HT12		14HT17		14HT09		14CT16
	13HT12		13KT05		14FT16		13IT10		14JT12		14IT05		14DT20
	13IT05		13KT12		14GT18		13IT16		13FT06		14IT14		14ET23
	13IT10		13LT04		14GT21		13IT20		13GE28J		14JT04		14FT04
	13IT13		13LT08		14HT03		13IT20R		13GE31J		14JT12		14GT05
	13IT20		14AT08		14HT17		13JT08		13GT11		13GE30J		14GT18
	13IT20R		14BT21		14HT24		13JT08R		13GT29		13GT29		14HT17
	13JT05R		14CT11		14IT08		13JT20		13IT05		13HT16		14IT08
	13JT08		14DT13		14JT14		13JT21		13IT16		13IT13		14DE14J
	13JT15		14DT15		14JT21		13KT12		13JT11		13LT08		14FE24J
	13JT20R		14DT19		13FT06		13KT18		13JT21R		14AE05J		14GE28J
	13KT05		14DT24		13GT11		14BT16		13JT25R		14DT10		
	13KT18		14ET04		13GT29		14CT06		13KT05R		14ET11		
	13LT08		14ET05		13HT12		14CT16		13LT11		14FT04		
	14BT15		14ET22		13HT17		14CT20		14BT09		14GT21		
	14BT16		14FT13		13IT10		14DT03		14BT15		14IT08		
14BT21	14GT15	13IT16	14DT13	14CT16	14IT14								
14CT11	14GT21	13IT20R	14DT24	14CT20	14JE43J								
14CT16	14HT03	13IT20R	14ET10	14DE16J	14JT18								
14DT13	14HT09	13JT08	14ET23	14DT19	14JT24								
14DT15	14HT17	13JT20	14ET28	14FE24J	13FT06								
14ET04	14HT20	13JT25	14FT13	14FT16	13GT24								
14ET10	14HT23	13KT05	14FT16	14GE29J	13JT21								
	14IT08	13KT12											