

27<sup>th</sup> March 2015

**URGENT FIELD SAFETY NOTICE**

**Oxoid Antimicrobial Testing Disc, CT0024B, CN10 Oxoid Gentamicin, Lot 1580419**

Customers are to be advised of the following:

A technical investigation has indicated that this lot of Oxoid Antimicrobial Testing Disc, CT0024B CN10 Gentamicin, Lot 1580419 may contain discs that have insufficient concentration of antibiotic.

Continued use of this lot could result in false resistance reporting.

Customers should review their internal quality control and test results reported using these lots and consider retesting and/or seek appropriate expert advice.

Accordingly, in keeping with our Quality Policy, we request that you destroy any remaining inventory of the lot listed above and contact Customer Services of your local Oxoid supplier who will issue a replacement.

This notice needs to be passed on to all who need to be aware within your organisation.

The Medicines and Healthcare products Regulatory Agency (MHRA) have been informed of this Field Safety Corrective Action.

If you experience any problems complying with this notice or you require any further information, please contact our Technical Support Department on +44 (0)1256 694238, or at [microbiology.techsupport.uk@thermofisher.com](mailto:microbiology.techsupport.uk@thermofisher.com)

Yours Sincerely,



**Colin Booth**  
**Global Director, Quality Assurance and Regulatory Affairs, Microbiology Products**