

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



This Annex I is considered as a supplementary attachment to the Field Safety Notice of FSCA-2019-09-11

FSCA Number: FSCA-2019-09-11

FSCA Title: VHK and VKMO Adult / Small Adult – Sterile Barrier Integrity

Affected Products:

- 701063877 - VKMO 71000 #QUADROX-i HMO 71000+VHK71000
- 701064518 - VKMO 50000 #QUADROX-i HMO 50000+VHK71000
- 701064523 - VKMO 70000 #QUADROX-i HMO 70000+VHK71000
- 701064525 - VKMO 78000 #QUADROX-i HMO 70000+VHK70000
- 701064526 - VKMO 51000 #QUADROX-i HMO 51000+VHK71000
- 701064567 - BE-VKMO 71000 #QUADR-i HMO71000+VHK71000
- 701067941 - VKMO 78000 #SQUADROX-i HMO 70000+VHK7000
- 701067942- VKMO 70000 #SQUADROX-i HMO 70000+VHK7100
- 701067948 - BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100
- 701067949 - VKMO 71000 #SQUADROX-i HMO 71000+VHK7100
- 701067951 - BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100
- 701067956 - BE-VKMO 70000 #SQUADR-i HMO70000+VHK7100
- 701067957 - BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100
- 701067962 - BO-VKMOD 71000 #SQUADROX-iD 71000+VHK7100
- 701067966 - VKMO 50000 #SQUADROX-i HMO 50000+VHK7100
- 701067968 - BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100
- 701067969 - VKMO 51000 #SQUADROX-i HMO 51000+VHK7100
- 701067972 - BE-VKMO 51000 #SQUADR-i HMO51000+VHK7100
- 701068197 - BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100
- 701062605 - VHK 71000#Venöses Reservoir VHK 71000
- 701063859 - BE-VHK 71000#Venöses Reservoir VHK 71000
- 701066420 - BO-VHK 71000-J#Venöses Reservoir VHK 710

Affected Timeframe:

Products manufactured before 4th March, 2019 with a valid shelf life of two years.

List of affected products

Country	Material No.	Material Description	Lot No.	Qty.
Argentina	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92218953	52
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92233270	200
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92224050	300
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239360	200
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92228714	300
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242275	1
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92243861	50

Urgent!
Field Safety Notice (FSN)
-Annex I-
List of affected products country-/ region-specific



Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242276	3
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92243882	42
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	4
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240161	328
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92235776	300
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	24
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	200
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249376	200
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250752	252
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253836	72
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253981	76
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255445	40
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255444	236
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255444	20
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255233	70
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260036	4
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261426	200
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250751	56
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255935	130
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255935	100
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262090	3
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262090	70
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262474	232
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262474	4
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262474	60
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264186	22
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266880	1
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266880	4
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268226	28
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92257299	275
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270888	100
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270888	25
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92271888	132

Urgent!
Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92275613	6
Argentina	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261651	294
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92235782	12
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92235782	32
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92239976	24
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92239976	40
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	28
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92256452	48
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262471	24
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262471	20
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262471	20
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	36
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	12
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	1
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	19
Argentina	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	24
Argentina	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234140	8
Argentina	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231051	4
Argentina	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231051	20
Argentina	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236492	8
Argentina	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236492	16
Argentina	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92250822	12
Argentina	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92250822	20
Argentina	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275627	20
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92223235	1
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92225413	51
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230616	2
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230616	1
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230616	249
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239734	147
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	37
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	60
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250773	249

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250918	231
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250760	23
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	1
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	13
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92257948	286
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92262473	184
Australia	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92267804	1
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92238610	24
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230626	16
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230627	4
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230627	60
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230627	60
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230627	1
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230627	16
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230627	2
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230627	1
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239713	60
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239713	20
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92235789	9
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92241484	130
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92242019	334
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92243470	13
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92235790	8
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92235790	60
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92235790	43
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	60
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	52
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92265357	21
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273465	26
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273559	52
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273560	41
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273526	20
Australia	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261684	51

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Australia	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239358	2
Australia	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239725	8
Australia	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92261954	20
Austria	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232559	23
Austria	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232882	19
Austria	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	42
Austria	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255233	42
Austria	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268225	42
Austria	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268841	42
Austria	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92271888	32
Austria	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	42
Austria	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261648	4
Austria	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267598	2
Austria	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92275614	3
Austria	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	42
Austria	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	65
Austria	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	35
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229034	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229196	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229196	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229196	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229268	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229268	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229268	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229268	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229268	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229538	3
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229538	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229538	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229538	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92230552	5
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92230552	8
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92230552	4

Urgent!
Field Safety Notice (FSN)
-Annex I-
List of affected products country-/ region-specific



Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92230552	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92230552	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92230552	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92234158	1
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92234158	3
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92234158	6
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92232924	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92232924	8
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92236440	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92236440	8
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92232617	3
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92238139	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92238139	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92237848	1
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92241495	3
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92246178	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92246178	1
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92246989	8
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92251173	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92251173	8
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92250943	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92250943	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92250943	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92251460	1
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92251460	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92252034	1
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92251821	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92252500	1
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92252500	7
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92252380	3
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92254677	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92257015	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92255755	4

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92255755	1
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92259540	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92261953	5
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92261953	3
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92262016	6
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92262016	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92262016	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92263871	3
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92263621	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92263534	4
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92265122	5
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92265834	5
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92266024	3
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92267370	1
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92267863	6
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92267863	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92268405	1
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92268405	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92269969	2
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92270134	3
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92271047	3
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92271047	11
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92271047	1
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92271047	16
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92271047	1
Belgium	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92271047	8
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	6
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	15
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	10
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230623	10
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	10
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	10
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92253979	20

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250785	10
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258533	20
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259153	20
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	10
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92253116	12
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	1
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	10
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	5
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	10
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	1
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	2
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271887	10
Belgium	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271887	10
Belgium	701067956	BE-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250812	1
Brazil	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92217196	1
Brazil	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92225392	168
Brazil	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92230543	3
Brazil	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92239557	5
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92241499	264
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	50
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92239547	336
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250783	52
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250785	114
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250776	100
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254623	95
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	138
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	1
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92256453	294
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	6
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271887	100
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272770	69
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274058	34
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274058	5

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274863	41
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275612	80
Brazil	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275612	1
Brazil	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238928	10
Brazil	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250839	6
Brazil	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261707	1
Brazil	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267037	34
Brazil	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261709	5
Brazil	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261709	4
Canada	701062605	VHK 71000#Venöses Reservoir VHK 71000	92241481	15
Canada	701062605	VHK 71000#Venöses Reservoir VHK 71000	92241481	10
Canada	701062605	VHK 71000#Venöses Reservoir VHK 71000	92250706	6
Canada	701062605	VHK 71000#Venöses Reservoir VHK 71000	92252305	6
Canada	701062605	VHK 71000#Venöses Reservoir VHK 71000	92252673	14
Canada	701062605	VHK 71000#Venöses Reservoir VHK 71000	92257464	10
Canada	701062605	VHK 71000#Venöses Reservoir VHK 71000	92272734	3
Canada	701064523	VKMO 70000 #QUADROX-i HMO 70000+VHK71000	92223952	3
Canada	701064523	VKMO 70000 #QUADROX-i HMO 70000+VHK71000	92232289	10
Canada	701064523	VKMO 70000 #QUADROX-i HMO 70000+VHK71000	92232289	12
Canada	701064523	VKMO 70000 #QUADROX-i HMO 70000+VHK71000	92232289	20
Canada	701064523	VKMO 70000 #QUADROX-i HMO 70000+VHK71000	92232288	20
Canada	701064523	VKMO 70000 #QUADROX-i HMO 70000+VHK71000	92250896	4
Canada	701064523	VKMO 70000 #QUADROX-i HMO 70000+VHK71000	92250896	16
Canada	701064523	VKMO 70000 #QUADROX-i HMO 70000+VHK71000	92252674	16
Canada	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	1
Canada	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	1
Canada	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92245064	1
Canada	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253389	6
Canada	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255431	38
Canada	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250749	13
Canada	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255430	21
Canada	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256451	3
Canada	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260967	16

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232912	70
Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232913	70
Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229775	100
Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250783	50
Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92253979	25
Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254624	48
Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250785	5
Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250785	22
Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250776	50
Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254623	50
Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274058	110
Chile	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275623	150
Chile	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229070	9
Chile	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92252113	1
China	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92230543	250
China	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92240109	192
China	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92240111	106
China	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92240110	146
China	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92240110	52
China	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92245980	150
China	701064518	VKMO 50000 #QUADROX-i HMO 50000+VHK71000	92228092	20
China	701064518	VKMO 50000 #QUADROX-i HMO 50000+VHK71000	92229871	1
China	701064518	VKMO 50000 #QUADROX-i HMO 50000+VHK71000	92230283	14
China	701064518	VKMO 50000 #QUADROX-i HMO 50000+VHK71000	92245978	25
China	701064518	VKMO 50000 #QUADROX-i HMO 50000+VHK71000	92246080	38
China	701064523	VKMO 70000 #QUADROX-i HMO 70000+VHK71000	92232289	25
China	701064523	VKMO 70000 #QUADROX-i HMO 70000+VHK71000	92232288	316
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92221308	8
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92221003	1
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92223545	8
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92224135	40
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92232315	335
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92234238	84

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92234237	84
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92233412	336
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92234251	80
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92234251	1
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92234251	3
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92238608	78
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92238608	244
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92238608	14
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92238616	84
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92238615	83
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92238609	336
China	701064525	VKMO 78000 #QUADROX-i HMO 70000+VHK70000	92242935	239
China	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92228910	50
China	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92239557	41
China	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92230511	50
China	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92240112	84
China	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92240113	84
China	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92243003	42
China	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92242936	10
China	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92242936	16
China	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92242936	16
China	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92245979	42
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245648	1
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92242944	210
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92248439	185
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92235768	190
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250005	33
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250002	300
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250006	141
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250733	35
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92251314	304
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252388	335
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250734	164

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250734	1
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250734	2
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252846	1
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252393	130
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92253068	2
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92253070	2
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254621	3
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255026	3
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255026	269
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255024	187
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255024	98
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256411	5
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255027	187
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256412	93
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256412	39
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256672	294
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250735	293
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256674	130
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250731	294
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258535	2
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258537	282
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92251279	294
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259646	2
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259645	6
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261424	209
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261423	293
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261421	250
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261417	294
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261418	1
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255232	9
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255232	229
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92257150	3
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92257150	290

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261416	292
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256450	10
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258811	233
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254678	31
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254678	15
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267470	294
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267472	293
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92263596	293
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267803	83
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267801	29
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267802	94
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267805	88
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267805	38
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268807	117
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268229	4
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268229	213
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268229	4
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92269292	250
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92269713	294
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92269452	150
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92269715	2
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270634	210
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270889	294
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270713	10
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270713	60
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272811	240
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272772	54
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272812	240
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272787	7
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92273481	16
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265688	1
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265688	293
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274590	85

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261799	100
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275213	10
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275206	1
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275206	125
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275215	100
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274594	82
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275225	100
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275217	1
China	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275221	88
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252390	200
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252391	6
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253390	3
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253389	19
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250753	193
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253981	46
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255445	33
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255431	144
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255430	56
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255233	58
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255233	58
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260034	50
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260588	42
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256451	200
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256451	84
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260968	115
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260967	16
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255931	294
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256747	283
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266160	110
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255932	155
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	35
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268840	126
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268840	20

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260927	10
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260927	44
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270632	10
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270888	10
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270971	54
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273656	11
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	4
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274054	12
China	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92275614	109
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	29
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92249683	43
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250007	78
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92249372	5
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250008	160
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250908	20
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250908	19
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255007	263
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254623	2
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255009	7
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255019	35
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255019	27
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258533	35
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259644	230
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259643	201
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262509	100
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262509	7
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254425	193
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251822	72
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251822	69
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261669	99
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92253116	93
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	65
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	49

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	49
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	9
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271831	80
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271887	27
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272808	11
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272807	2
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272807	9
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274059	74
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274059	6
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274059	10
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274058	3
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275622	14
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275905	36
China	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275905	130
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92240740	1
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236493	100
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92249684	75
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92249684	27
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92250822	24
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92250822	23
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92250822	100
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92252186	16
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92252187	10
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92268519	34
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92268519	50
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92269707	10
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92269707	100
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92269707	15
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92267867	42
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92268617	42
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92263659	56
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275627	14
China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275626	4

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

China	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275629	40
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229070	64
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	8
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92231289	44
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238925	6
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92239359	5
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92243775	22
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92243775	10
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238928	22
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238928	103
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238929	168
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238929	32
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238927	210
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250831	124
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250832	120
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	20
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92259064	140
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92259064	25
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92259064	2
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92259064	6
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92255949	133
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92259649	119
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250834	126
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250835	128
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	7
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	3
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261707	83
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92269381	116
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261709	14
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261710	1
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261710	34
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261708	10
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261708	32

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250840	84
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275625	12
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275620	4
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275619	84
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275930	6
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275930	16
China	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275931	75
Colombia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92239976	190
Colombia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92246454	50
Colombia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	100
Colombia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229070	10
Colombia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	41
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250809	72
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92254661	60
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92262019	60
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92271891	60
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92272972	60
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273559	30
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273559	30
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273526	30
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261816	21
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261816	1
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250806	67
Czech Republic	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261685	30
Czech Republic	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92256155	5
Denmark	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274606	1
Denmark	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92263659	8
Denmark	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92259064	11
Ecuador	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	80
Ecuador	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229776	140
Ecuador	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255019	50
Ecuador	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258533	20
Ecuador	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	17

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Ecuador	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	3
Ecuador	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	40
Ecuador	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	6
Finland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266160	20
Finland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270971	10
France	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	4
France	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267036	1
France	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92265489	3
France	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250839	2
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92232517	42
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92236823	30
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92236823	12
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92232653	14
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92232653	70
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92237551	16
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92237551	26
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92235698	2
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92235698	40
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92239622	126
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92238392	3
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92238392	36
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92238957	68
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92238957	57
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92238957	1
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92241481	10
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92241481	68
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92241481	65
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92242929	4
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92242929	62
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92242929	60
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92247464	30
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92248209	18
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92248209	36

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92248209	70
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92248209	2
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92250707	44
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92250707	40
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92250706	14
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92250706	19
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92252305	36
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92252895	15
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92252895	27
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92252673	13
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92252673	57
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92255309	35
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92255309	7
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92255352	31
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92255352	20
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92255352	33
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92257464	19
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92257464	13
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92257590	47
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92257590	37
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92260652	15
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92260652	27
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92259881	19
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92259881	23
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92265309	4
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92265309	39
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92265309	40
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92267707	38
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92267707	46
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92269705	20
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92269705	22
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92270192	40
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92270192	2

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92273823	42
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92272734	6
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92272734	50
Germany	701062605	VHK 71000#Venöses Reservoir VHK 71000	92272734	25
Germany	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92230552	13
Germany	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92232617	7
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	1
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242958	20
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250755	1
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264345	1
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264186	8
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266880	16
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266160	34
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	9
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	15
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	20
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268809	25
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269295	8
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	5
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92257299	7
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268840	2
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260927	35
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92271888	36
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274054	4
Germany	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274073	15
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92219222	2
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92223235	2
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230616	12
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230617	12
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230617	12
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	2
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	6
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	4

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	8
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	8
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250769	1
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271500	32
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271500	10
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271500	8
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271883	1
Germany	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271883	11
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	8
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	2
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	2
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	102
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	9
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92236985	5
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92236985	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92236985	46
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229776	29
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229776	33
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92239555	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	18
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240741	20
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	72
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92235782	102
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92241729	8
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	4
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92245991	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92239976	52
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92246454	21
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	3

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	40
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92235784	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92235784	9
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92249683	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250008	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92252108	3
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250783	9
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250783	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92253979	20
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92253979	40
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254624	5
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250785	2
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250776	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254623	4
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255009	20
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92256409	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92257017	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258533	54
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	51
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259153	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259153	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92260581	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262155	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262471	5
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262509	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	42
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251822	12
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251822	10
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	6
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	15

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	16
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	6
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92266866	42
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	10
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	9
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	18
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	36
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	42
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	4
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	20
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271499	21
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271499	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	20
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	8
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	22
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272807	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274059	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274863	9
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274863	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275218	15
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275218	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275623	18
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275623	6
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275622	5
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275621	1
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275905	2
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275904	8
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	6
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	18

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	11
Germany	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	42
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92229779	30
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92229779	44
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230626	6
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92238611	19
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230627	25
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230627	4
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230627	73
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	1
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	23
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	20
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	30
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	23
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92249680	56
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92249680	40
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250807	21
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250801	10
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250795	39
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92253053	1
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92251330	1
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92251330	25
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92251330	25
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250810	4
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92253054	42
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92252387	3
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250809	12
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250809	42
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250798	36
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92254661	20
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92254661	16
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92262019	25
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92262019	15

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92262019	40
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92262019	25
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92262019	6
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273559	20
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273526	1
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261816	1
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261816	19
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250806	23
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261684	18
Germany	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261685	30
Germany	701067956	BE-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92221252	144
Germany	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92256155	16
Germany	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92256155	15
Germany	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92230632	2
Germany	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92239729	1
Germany	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236493	10
Germany	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92249684	7
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239910	6
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239910	4
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239910	8
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239910	12
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239910	8
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239911	1
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239911	5
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239911	1
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239911	4
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239911	8
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239911	2
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239911	12
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239911	12
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92242278	4
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92242278	8
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92242278	2

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92243935	12
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249682	1
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249682	5
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	12
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	7
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	4
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	4
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	12
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250827	3
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250827	8
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250827	12
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250827	7
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250823	6
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250823	12
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250823	4
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250823	1
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	11
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	12
Germany	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	2
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92223242	20
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229070	1
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	5
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238928	6
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238928	6
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238929	6
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250831	4
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	2
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	6
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	2
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	6
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250836	6
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250836	6
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	1

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	6
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	3
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	2
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	20
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92259064	1
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92259064	5
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	2
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	1
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	8
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	6
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267036	3
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267036	8
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267036	7
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267036	8
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267036	6
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250839	8
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250839	4
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250839	8
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250839	15
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250839	7
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261709	8
Germany	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275932	1
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92227177	4
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92227177	4
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92227177	4
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92223244	6
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92223244	16
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92223244	20
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92223245	16
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92223245	20
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92246716	10
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92246716	10
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92246716	10

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92262020	1
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92257006	7
Germany	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92258546	12
Greece	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234139	15
Guatemala	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92262020	4
Hong Kong	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250749	2
Hong Kong	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	2
Hong Kong	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250777	18
Hong Kong	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272808	30
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232882	144
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92221565	100
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92221565	2
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92224050	3
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234234	106
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234234	49
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234236	1
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239360	64
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240735	225
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240733	150
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240733	25
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240737	230
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230611	48
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230611	65
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240010	250
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240010	85
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242276	198
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92243882	250
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92243882	2
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244483	21
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240161	1
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92245992	172
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92246318	100
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92246318	100

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92246318	60
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92235776	34
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	85
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	53
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242958	9
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	120
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	11
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	84
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252111	201
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250747	336
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252392	42
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252391	135
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253390	113
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253389	187
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253836	7
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253981	7
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255445	45
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255444	22
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255431	70
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250749	132
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250749	41
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250754	52
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256592	194
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256591	132
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260588	84
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250751	200
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262091	76
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262090	194
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264186	172
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	20
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	58
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250757	106
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266880	206

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266881	294
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266882	198
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255932	74
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268226	210
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	9
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268809	100
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268809	47
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255933	279
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255933	11
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	4
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270631	294
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270888	148
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92271318	294
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270971	42
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273656	38
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	24
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274054	126
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261648	160
India	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274606	8
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229066	40
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229064	100
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231050	120
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231049	39
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231049	100
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231049	40
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92239729	36
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92239729	50
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234139	20
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234139	100
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92240740	100
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236492	25
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236492	25
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236492	30

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236492	50
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92249684	50
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92250822	4
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92250822	5
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92252186	100
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92252187	50
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92252187	50
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92252189	15
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92252189	100
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92267866	126
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92269707	1
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92263659	20
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275627	8
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275626	28
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275626	8
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275624	42
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275630	20
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275628	42
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275933	30
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275933	8
India	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275933	4
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92219280	1
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232559	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232883	15
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92221565	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239360	25
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239361	15
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239361	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242275	30
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230611	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	5

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244485	1
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230884	27
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244483	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242958	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242958	1
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	12
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	3
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	7
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252111	15
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	20
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253390	5
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253981	25
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255431	11
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250749	8
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250754	20
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250754	21
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256592	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260035	23
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260967	6
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261426	9
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250751	25
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262090	8
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92263459	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264345	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264345	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	20
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266880	10
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	8
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268841	6

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	15
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	8
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	12
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	2
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	9
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274054	18
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274073	11
Ireland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274606	1
Ireland	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	5
Ireland	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	1
Ireland	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	8
Ireland	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229776	18
Ireland	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	3
Ireland	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	16
Ireland	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	2
Ireland	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	2
Ireland	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	1
Ireland	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271887	3
Ireland	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	11
Ireland	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92223245	6
Ireland	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92243940	3
Ireland	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92250845	10
Ireland	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92262020	2
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92228776	2
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230332	1
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232559	28
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232559	50
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232883	5
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232883	21
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92221565	150
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234236	5
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	40
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239361	80

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240737	25
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230611	50
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230884	231
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240161	3
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242958	40
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	20
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	1
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	6
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252111	18
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	9
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	13
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253391	6
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253390	2
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253389	18
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253389	27
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253836	21
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253836	70
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253836	30
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256592	1
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256592	10
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260036	80
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250755	26
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260035	74
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250751	7
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250751	6
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255935	1
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262474	30
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	3
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	7
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250757	2
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266160	10
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266882	42
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268226	5

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	20
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	7
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	8
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	36
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	24
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	15
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	3
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	33
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	10
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268841	60
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269295	28
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269295	3
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269295	12
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269295	30
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	2
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260927	39
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260927	12
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270888	1
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270971	9
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274054	2
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274054	9
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274054	16
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274073	15
Italy	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274588	14
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92226147	1
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92223235	2
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92223235	37
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230612	4
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230612	2
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230612	10
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92225413	10
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92225413	100
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230613	296

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230616	8
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239734	1
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92242272	84
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230617	1
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230617	58
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230617	242
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92245651	15
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239705	1
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239705	2
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239705	158
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92246179	5
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92246179	90
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92246179	20
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92246179	40
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92246179	35
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92246179	20
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92248438	5
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92248438	50
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92248438	29
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	1
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	50
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	10
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	51
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	20
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	13
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250773	1
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250773	2
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250760	51
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250760	27
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250760	50
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250760	71
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250760	62
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250760	52

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250762	30
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250762	17
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250762	2
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92256675	73
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92256675	49
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92256675	4
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	6
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	2
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	15
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	21
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	30
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	28
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92257948	6
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92262473	5
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250769	37
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250769	46
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250764	2
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250764	20
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250764	120
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250764	34
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250764	23
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92267804	6
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92267804	2
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92267804	33
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92262018	18
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92262018	35
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250770	10
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250770	32
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250770	41
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250770	20
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250770	14
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250770	1
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92260101	42

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92255940	62
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271317	31
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271317	17
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271317	3
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271317	7
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271317	20
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271317	95
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271500	41
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271500	18
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271500	2
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271500	30
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271500	19
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271883	19
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271883	20
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271883	38
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271883	37
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92274864	38
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92274864	26
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92274864	62
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92255074	7
Italy	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92255074	25
Italy	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	30
Italy	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92252108	1
Italy	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	1
Italy	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254590	1
Italy	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261669	50
Italy	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	4
Italy	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275242	23
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230624	4
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92229779	19
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92229779	70
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92229779	25
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92229779	22

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92238610	40
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230626	2
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230626	30
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92238611	1
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92241498	84
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92236308	10
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239713	5
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239713	41
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92235789	1
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	10
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	10
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	29
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92249680	15
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92249680	20
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92249680	15
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92249680	10
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92249680	51
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92249680	18
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250801	22
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250795	1
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250795	45
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92253053	1
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92253053	12
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92253053	20
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92253053	35
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92251330	4
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92251330	40
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92251330	50
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92252387	3
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92252387	7
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92252387	1
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92265357	21
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250798	1

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250798	53
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92254661	10
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92254661	15
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92254661	4
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92269299	1
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92262019	9
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92262019	20
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92262019	50
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92262019	10
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92271891	11
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92271891	10
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92272972	10
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92272972	12
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92272972	1
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273559	20
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273559	5
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273559	40
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273559	1
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273560	1
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273526	2
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273526	9
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273526	22
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250806	26
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250806	16
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250806	5
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250806	30
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250806	1
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261684	4
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261684	10
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261684	1
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261685	14
Italy	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261685	9
Italy	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92222591	5

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Italy	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92222591	3
Italy	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92222591	2
Italy	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92238437	5
Italy	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92256155	5
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92230650	50
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92230650	9
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92230650	7
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92230650	11
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92230650	6
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92232906	16
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92232906	11
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92240115	5
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92240115	37
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92236490	54
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92240118	4
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92240118	30
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92240118	1
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92240118	1
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92240116	1
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92240116	17
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92240116	10
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92240116	14
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92240117	42
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250819	13
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250819	29
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250813	7
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250813	3
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250813	1
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250813	30
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250813	1
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250815	32
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250815	10
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250944	9

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250944	1
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250944	2
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250944	8
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250877	21
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250877	1
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92268980	2
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92268980	18
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250820	12
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250820	20
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92250820	4
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92268407	20
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92270729	16
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92269994	9
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92269994	3
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92269994	20
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92268193	27
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92268193	5
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92268192	2
Italy	701067962	BO-VKMOD 71000 #SQUADROX-iD 71000+VHK 71	92268192	30
Italy	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229065	29
Italy	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92230632	70
Italy	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234139	18
Italy	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234139	4
Italy	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234139	3
Italy	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234140	13
Italy	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234140	30
Italy	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231051	12
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239358	50
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239218	35
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239218	9
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239725	21
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239910	2
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239911	5

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92243935	12
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92243935	6
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92243935	10
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92243935	2
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249682	10
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249682	4
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249682	5
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249682	11
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249682	3
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249682	5
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	2
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	11
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	3
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	4
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	9
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	14
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92249681	2
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250827	5
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250827	6
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250823	14
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	3
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	7
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	5
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	2
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	6
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	4
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	11
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	5
Italy	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92261954	22
Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	1
Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	1
Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92231289	10
Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238928	10

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238928	1
Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238929	1
Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	2
Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250836	2
Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	4
Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92259064	2
Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267036	10
Italy	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261709	2
Italy	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92227177	30
Italy	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92223245	25
Italy	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92243940	10
Italy	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92250845	1
Italy	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92250845	2
Italy	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92262020	4
Italy	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92262020	7
Italy	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92262020	4
Italy	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92258545	1
Italy	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92258545	3
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92225981	168
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92225934	336
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92241400	60
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92250011	166
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92246706	170
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92246706	166
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92250012	1
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92250012	130
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92250012	205
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92250137	298
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92252381	167
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92252381	1
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92259882	1
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92259882	133
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92263254	132

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92263254	162
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92262017	1
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92262017	293
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92263256	217
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92263256	1
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92263255	294
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92265488	4
Japan	701066420	BO-VHK 71000-J#Venöses Reservoir VHK 710	92265488	132
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92224051	30
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92224051	150
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230612	36
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230612	100
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230612	70
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92225413	50
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230616	64
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92245651	57
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239705	133
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239705	30
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250762	245
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	100
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	40
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92262018	35
Japan	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92262018	197
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92228623	26
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230624	254
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230626	170
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230626	112
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92236308	200
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92230627	90
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	60
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	13
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92239714	5
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250801	70

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250795	157
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92253053	15
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92251330	92
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92252387	108
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92252387	24
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250799	126
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250798	70
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250798	70
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250798	64
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92254661	1
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92269299	125
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92262019	34
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92271891	3
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92272972	17
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273559	17
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273559	1
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92273559	78
Japan	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92261685	1
Japan	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92227552	32
Japan	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239910	25
Japan	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92239910	5
Japan	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92250823	5
Japan	701067968	BO-VKMO 50000 #SQUADR-i HMO50000+VHK7100	92252358	16
Japan	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92246716	12
Japan	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92243940	20
Japan	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92243940	10
Japan	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92250010	70
Japan	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92250010	14
Japan	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92250009	34
Japan	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92250009	50
Japan	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92250845	28
Japan	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92262022	42
Japan	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92262020	19

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Japan	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92262020	1
Mexico	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260967	100
Mexico	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	38
Mexico	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259207	59
Mexico	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259644	22
Mexico	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92256452	81
Mexico	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275904	80
Mexico	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92235789	200
Mexico	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250795	94
Mexico	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92250810	206
Mexico	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250836	60
Mexico	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267037	50
Mexico	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261710	7
Mexico	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275620	38
Mexico	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275930	20
Mexico	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92218147	49
Mexico	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92223245	1
Netherlands	701062605	VHK 71000#Venöses Reservoir VHK 71000	92238392	3
Netherlands	701062605	VHK 71000#Venöses Reservoir VHK 71000	92250706	1
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92226958	2
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229034	8
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229268	4
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92229538	5
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92232654	10
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92238139	2
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92237848	9
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92241495	7
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92246178	1
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92250943	8
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92252034	4
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92251821	3
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92252500	2
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92252380	2

Urgent!
Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92254677	1
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92257015	1
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92255755	5
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92257323	4
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92257323	4
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92259540	1
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92261573	5
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92261953	6
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92261953	1
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92262016	6
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92263871	2
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92263621	3
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92265273	5
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92266024	1
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92266024	6
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92266975	5
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92267370	4
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92267863	2
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92268405	16
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92268405	5
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92269969	2
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92269706	10
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92270134	7
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92270242	42
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92271047	30
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92271047	56
Netherlands	701063859	BE-VHK 71000#Venöses Reservoir VHK 71000	92272135	10
Netherlands	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	1
Netherlands	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	1
Netherlands	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229065	3
Netherlands	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229064	6
Netherlands	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231049	3
Netherlands	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	3

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Netherlands	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	4
Netherlands	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	3
Netherlands	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250839	4
Netherlands	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250839	3
Paraguay	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	108
Paraguay	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	2
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234234	50
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	4
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242275	2
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92245992	4
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92235777	16
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242958	79
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	1
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92263459	2
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264345	8
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266880	8
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	30
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	7
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	2
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	20
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	13
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	5
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260927	10
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	15
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274054	70
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261648	100
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274073	150
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274073	50
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267598	80
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261649	294
Poland	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92275614	56
Poland	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92228570	72
Poland	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229065	28

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Poland	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229066	18
Portugal	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258811	7
Portugal	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92264185	1
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92236985	100
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	100
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240741	50
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	1
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92241729	21
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	20
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	15
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	5
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92245991	79
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92239976	30
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250783	30
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250776	50
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254623	2
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255019	50
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258533	50
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259063	2
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259153	6
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250777	1
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250777	50
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92260581	11
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92260581	100
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92256452	1
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262472	37
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262471	31
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262471	2
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254425	3
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254425	36
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	6
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	8
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263258	1

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263258	64
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251822	49
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	10
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	10
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	40
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271499	11
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	8
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	38
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271831	20
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271887	10
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272770	1
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272770	11
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272808	21
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272808	50
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274059	1
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274058	30
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275612	1
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275623	30
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275623	90
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275904	18
Portugal	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275904	39
Portugal	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92241484	1
Portugal	701067951	BO-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92251330	99
Portugal	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92222591	1
Portugal	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92238437	59
Portugal	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92256155	1
Portugal	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92272001	14
Portugal	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267036	10
Portugal	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92265489	1
Portugal	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250839	1
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244482	3
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92240159	333
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245649	92

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245648	71
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245648	100
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92246011	335
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92246316	164
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245650	1
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92246317	160
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92247781	336
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92248439	48
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92235768	116
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250005	126
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250002	29
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250733	300
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250734	45
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250745	336
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252845	336
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252844	335
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252846	290
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252393	50
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252393	3
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256411	288
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255027	107
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258535	5
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258535	1
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92260591	95
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261424	1
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261423	1
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261422	5
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92262088	2
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256450	100
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256450	80
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255929	9
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265471	1
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265471	11

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265471	13
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92266878	100
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267472	1
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267474	201
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267475	2
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267802	195
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261645	4
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261645	109
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268230	168
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268228	9
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268229	3
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268229	70
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265686	2
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268843	200
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265687	38
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265687	255
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265687	1
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92269452	135
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92269452	9
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92269715	40
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270724	57
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270639	50
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272771	50
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272771	10
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92273480	14
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272787	100
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272787	50
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272787	19
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274591	100
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274591	53
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274591	31
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274591	110
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274590	40

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274590	169
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92251281	44
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92251281	250
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256024	44
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256024	250
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275225	100
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275221	59
Russia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275221	110
Russia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234234	76
Russia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252391	85
Russia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256591	30
Russia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262090	12
Russia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255932	6
Russia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255932	2
Russia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	45
Russia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270888	10
Russia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274606	4
Russia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267598	87
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255019	30
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	1
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259207	6
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250777	57
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259643	93
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254425	1
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	8
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263258	5
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272807	100
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274059	4
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275622	25
Russia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275622	29
Russia	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92250822	2
Russia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92223242	4
Russia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92223243	6

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Russia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238925	32
Russia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	1
Russia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	2
Russia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	1
Russia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	40
Russia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	1
Russia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	19
Russia	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92269381	10
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92249679	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92235768	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250005	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250006	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250733	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252388	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252393	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254622	3
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254621	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254621	80
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256674	40
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258535	160
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255927	2
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255231	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261418	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92257150	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261416	1
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92253109	7
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268807	176
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270639	50
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272771	32
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272787	70
Serbia	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272787	48
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	20
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	30

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242958	100
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250754	98
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256591	2
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262474	30
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264186	60
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264186	24
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	36
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268841	100
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	40
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	5
Serbia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	55
Serbia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	60
Serbia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92241089	63
Serbia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	3
Serbia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92241497	84
Serbia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230623	150
Serbia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254623	20
Serbia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264150	1
Serbia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271499	2
Serbia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275622	1
Serbia	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	30
Serbia	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231049	4
Serbia	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92252189	10
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232883	57
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232883	1
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92221565	8
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92233269	335
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92233271	44
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92233270	63
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92236306	420
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239232	63
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242268	146
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92236307	93

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92236307	242
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92245993	131
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92245064	331
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92245064	2
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	4
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249376	15
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249376	95
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250758	133
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250758	203
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250912	132
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252391	90
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260034	200
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250755	255
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261425	178
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261425	116
Singapore	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92263459	161
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92221567	2
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	5
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92236985	10
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	6
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	5
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	5
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	2
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92235782	6
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92235782	6
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92235782	5
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	20
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	10
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	5
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	15
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	5
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	2
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262509	15

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	2
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	5
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	5
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	4
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275242	10
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275218	5
Singapore	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	35
Singapore	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229065	8
Singapore	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229066	10
Singapore	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229064	2
Singapore	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231049	5
Singapore	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234139	25
Singapore	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92252186	10
Singapore	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92275630	20
Singapore	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92223242	10
Singapore	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92223243	3
Singapore	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92231289	2
Singapore	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238928	2
Singapore	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	3
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92228714	20
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92241946	10
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240737	10
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242275	20
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92243861	40
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92243861	20
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242276	40
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	40
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	40
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	31
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	9
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252390	40
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253389	1
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260035	60

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266160	20
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268840	60
Slovakia	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268840	10
South Africa	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92232917	1
South Africa	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239366	2
South Africa	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92243862	2
South Africa	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	10
South Africa	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92223242	18
South Africa	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92223243	3
South Africa	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92252113	1
South Africa	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	4
South Africa	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250836	6
South Africa	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250836	5
South Africa	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	43
South Africa	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	1
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232559	5
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232559	90
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232559	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232559	15
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232882	50
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232882	4
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92221565	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92221565	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234234	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234234	15
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	13
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239360	3
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92228714	7
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92228714	3
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92228714	6
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239361	5
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239361	4
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239361	11

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240733	21
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92241946	15
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92241946	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242275	2
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230611	30
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230611	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242276	2
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	90
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	29
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244485	11
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230884	1
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230884	60
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230884	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230884	6
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244483	80
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244483	3
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244483	15
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244483	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244483	49
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	4
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242958	40
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	2
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	15
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	26
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	3
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	5
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	40
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	35
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252390	20

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252391	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253390	50
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255445	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255445	40
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255444	2
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255431	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255431	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255430	3
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255430	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255233	30
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255233	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256591	30
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260036	11
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260034	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260034	1
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260034	4
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260034	11
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260035	27
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260035	19
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261426	2
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261426	2
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255935	30
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92263459	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	2
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	1
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	30
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	30
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250757	17
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266880	19
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255932	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255932	11
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268841	20

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268841	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273527	24
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273656	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273656	20
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273656	30
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273656	110
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273656	26
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274054	1
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274073	10
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274606	60
South Korea	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267598	40
Spain	701062605	VHK 71000#Venöses Reservoir VHK 71000	92250706	2
Spain	701062605	VHK 71000#Venöses Reservoir VHK 71000	92265309	1
Spain	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239739	1
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232883	30
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92224050	1
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234236	25
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	3
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	37
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239361	22
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239361	28
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239361	9
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240733	20
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240733	9
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240737	25
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242275	3
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230611	30
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230611	17
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244483	20
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244483	50
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92245992	20
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	15
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	3

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	20
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	4
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	20
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	6
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	3
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	7
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	2
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	6
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249376	3
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249376	3
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	5
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	8
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	2
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	8
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	7
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	12
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252111	3
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252111	12
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252111	12
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252111	5
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252111	34
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	7
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252390	60
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252390	15
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253390	31
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253836	40
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253981	10
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253981	19
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255444	11
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250749	49
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255430	24
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256591	36
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256591	24

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260967	25
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261426	35
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262090	1
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92263459	60
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266160	60
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266882	11
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268227	42
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	30
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	1
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	2
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	18
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268809	50
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	5
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260927	5
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260927	55
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273656	10
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273656	15
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	24
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274073	10
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274606	1
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274606	1
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267598	1
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92275613	38
Spain	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92275613	60
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92223235	2
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230612	29
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239734	20
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230617	1
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92230617	10
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92245651	10
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92245651	2
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239705	12
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	26

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92239706	60
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	50
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250763	10
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92257948	2
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250764	11
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92262018	9
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250770	8
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92255940	22
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271317	37
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92271500	50
Spain	701067948	BO-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92255074	10
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	8
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229775	40
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92236985	15
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92236985	50
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92236985	24
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229776	20
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	8
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240741	15
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92241089	6
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	18
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	2
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	15
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	25
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230623	26
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230623	25
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	18
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	20
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	7
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	18
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	7
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	15
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	10

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	55
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	50
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92253979	20
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250785	40
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258533	30
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	10
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	50
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262472	30
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	50
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	10
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	15
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	30
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	25
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	25
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271831	30
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271831	20
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272808	5
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274058	15
Spain	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275612	17
Spain	701067956	BE-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250811	3
Spain	701067956	BE-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250811	20
Spain	701067956	BE-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250811	60
Spain	701067956	BE-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250812	5
Spain	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92238437	30
Spain	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92238437	50
Spain	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92272000	10
Spain	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92272001	1
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92222085	1
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92227174	1
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229065	1
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229065	6
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229065	3
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229065	3

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229065	3
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229065	1
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229066	8
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229066	1
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229066	4
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229066	2
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229066	1
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229064	2
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229064	5
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229064	1
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92230632	1
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92230632	5
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231049	1
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231049	7
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231049	1
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92239729	3
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234139	5
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234139	3
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234139	5
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231051	2
Spain	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231051	5
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92223242	5
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	2
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	3
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	5
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	2
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92243775	5
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92243775	5
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238929	3
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92252113	2
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	5
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	2
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	1

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	5
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	1
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	5
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250834	2
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	3
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	4
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	4
Spain	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267036	3
Spain	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92243940	1
Spain	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92250845	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242268	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92236307	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230884	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244483	48
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92245993	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242958	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	2
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	6
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253390	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255444	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255431	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250749	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250754	2
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250754	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256592	2
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255233	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255233	2

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256591	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260968	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260968	10
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256747	11
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261426	3
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255935	4
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255935	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255935	3
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262090	5
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262474	4
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92263459	3
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92263459	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92263459	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264345	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264345	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	2
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	9
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250757	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266880	3
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266880	10
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266160	14
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266160	15
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255932	2
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255932	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268226	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	24
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255933	4
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268841	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	1
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270971	11
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92271888	10
Sweden	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273656	24

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Taiwan	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92230543	1
Taiwan	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92230543	7
Taiwan	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92230543	3
Taiwan	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92230543	20
Taiwan	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92230543	10
Taiwan	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92240109	18
Taiwan	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92240111	20
Taiwan	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92242932	10
Taiwan	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92242932	20
Taiwan	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92242932	20
Taiwan	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92242932	10
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92249372	5
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250008	5
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250008	20
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250908	5
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250783	5
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255007	10
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255007	20
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	10
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259207	10
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263258	20
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263258	20
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	5
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	5
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	20
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274058	20
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275622	10
Taiwan	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275622	30
Thailand	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248437	17
Thailand	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	2
Thailand	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	20
Thailand	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	61
Thailand	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264345	50

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Thailand	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268226	50
Thailand	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	50
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92217435	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92217435	89
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92217436	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92230541	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92232555	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92232554	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92232917	20
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92225411	2
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92225914	111
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92225914	130
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92225914	95
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92234232	31
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92234232	200
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92234233	109
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92234233	49
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92234233	10
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236546	168
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92230607	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92231393	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236545	8
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236983	21
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236984	335
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92238613	168
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92238612	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239362	146
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92238614	26
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92238614	44
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239739	10
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239739	322
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239739	2
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239366	334

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239740	98
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92240722	53
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92240722	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92240722	12
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239741	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92243864	8
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92243864	36
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92243863	327
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92243862	34
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92243862	252
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92243862	33
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92235772	231
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92235772	101
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92235772	2
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92240158	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92243945	294
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92243946	335
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244482	34
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244482	4
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244482	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244481	108
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244481	228
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244170	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244170	2
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244170	153
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244170	34
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244170	139
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92244170	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245647	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92240159	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245648	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245648	162
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245650	1

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245650	2
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245650	56
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92245650	276
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92246317	83
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92247780	50
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92242944	126
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92247778	226
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92247778	110
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92247779	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92248439	53
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92249678	34
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92249679	200
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92249679	62
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92249679	73
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92235768	28
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250002	5
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250002	2
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92249386	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92251315	278
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252112	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252417	152
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252417	2
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252389	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250734	91
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250734	3
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92252393	152
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92253069	336
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92253068	334
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92253071	30
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92253070	248
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92253070	85
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254620	134
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254621	6

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254621	3
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250739	294
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250730	294
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255024	9
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256412	100
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256673	294
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259645	239
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92260593	168
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255927	292
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92260591	191
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261422	2
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261421	24
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261418	292
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255232	36
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92262089	42
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92262088	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92264185	3
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265469	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92266099	3
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265471	4
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92266879	126
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254678	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254678	100
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254678	145
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92266878	126
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92266157	194
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92266157	100
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267471	42
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92253109	5
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267473	252
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267474	87
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267474	6
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255930	226

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255930	62
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255930	6
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267475	4
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267475	287
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267803	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267801	2
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267801	54
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267801	206
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92267802	5
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261645	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261645	2
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261645	7
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268228	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261863	3
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268807	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92269292	2
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265743	134
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268843	94
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270724	109
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270634	84
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270637	292
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272771	144
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92273480	280
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92273481	176
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274592	168
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261799	97
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261799	94
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275215	100
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275215	1
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274594	211
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275225	10
Turkey	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275221	9
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232882	50

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92241946	4
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240737	6
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	57
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244485	12
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244485	1
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249380	4
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252111	30
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	5
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252390	1
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253390	40
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260034	8
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250755	12
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268840	30
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274606	50
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92275613	22
Turkey	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274588	28
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92226476	2
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92221567	101
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232912	14
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	6
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	130
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232913	13
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229775	16
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229775	150
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	2
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230623	100
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230623	17
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92235782	133
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92245990	74
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	16
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	12
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92245991	4
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	37

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92249372	326
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250008	108
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250783	90
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254624	6
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250785	97
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250776	75
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255019	26
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258533	14
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	36
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259063	136
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	51
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250777	80
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250777	39
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92256452	164
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262472	59
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254425	41
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254425	17
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	1
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	29
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263258	7
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251822	82
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261669	25
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261669	100
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92253116	100
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	12
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	18
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	39
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	26
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	10
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	7
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261672	9
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	8
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	14

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	20
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271499	9
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271499	60
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	20
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271831	60
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271887	50
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272770	99
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272808	30
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274058	16
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274058	41
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274058	20
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275193	12
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275193	14
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275611	123
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275242	208
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275612	3
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275218	17
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	1
Turkey	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	54
Turkey	701067956	BE-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250811	1
Turkey	701067956	BE-VKMO 70000 #SQUADR-i HMO70000+VHK7100	92250812	33
Turkey	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92229064	10
Turkey	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92231049	10
Turkey	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92234139	10
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	25
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	5
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92243775	7
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92243775	10
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238928	12
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238928	3
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92252113	5
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250836	20
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250836	20

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92253982	10
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	10
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267036	25
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92265489	5
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92265489	5
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92265489	5
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92265489	5
Turkey	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92265489	15
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92217347	2
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92219353	1
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92226368	336
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92228530	36
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92219355	10
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92228132	313
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92223945	10
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92226369	336
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92231285	290
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92231286	42
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92231286	294
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92235811	34
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92241057	292
United Arab Emirates	701063877	VKMO 71000 #QUADROX-i HMO 71000+VHK71000	92240110	5
United Arab Emirates	701064523	VKMO 70000 #QUADROX-i HMO 70000+VHK71000	92232289	40
United Arab Emirates	701064526	VKMO 51000 #QUADROX-i HMO 51000+VHK71000	92228910	30
United Arab Emirates	701064567	BE-VKMO 71000 #QUADR-i HMO71000+VHK71000	92222529	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92232918	41
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92232915	84
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92224049	210
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92224049	102
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92228550	336
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92232917	48
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92232917	36
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92232916	332

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92233266	168
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92233268	128
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92233265	284
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92233265	50
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92234232	65
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92234232	40
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236545	328
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236603	336
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236555	336
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236604	336
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92227586	336
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236605	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236605	28
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236605	138
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236605	47
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92236605	122
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92230608	336
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239362	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239365	60
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239365	95
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92239365	17
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92238614	239
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92238614	3
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92238614	23
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92235768	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254622	167
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254620	13
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254620	147
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254621	201
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92250735	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258536	249
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258536	2
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258535	83

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258535	43
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258537	7
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92258537	5
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259646	250
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259645	45
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259645	4
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259648	252
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259647	294
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92260592	294
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92260591	8
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92260966	146
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92260966	22
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92260965	14
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92260965	280
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92260964	294
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255231	293
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261424	42
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261422	83
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261422	118
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261422	2
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261421	20
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255232	20
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261416	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92262088	240
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92262088	51
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256450	100
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256450	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92256450	3
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92264185	240
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92264185	50
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92264346	96
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265469	100
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265469	25

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255929	28
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92255929	155
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259439	68
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259439	226
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92266115	126
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92266099	123
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265471	119
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265471	148
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254678	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92254678	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92253109	145
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92253109	136
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261645	171
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268228	160
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268228	47
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268228	76
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261863	119
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261863	119
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261863	53
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268231	294
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265686	7
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265686	277
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265686	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265686	2
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92268808	168
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92265743	160
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270724	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92270724	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92272771	3
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259097	60
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92259097	234
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261802	60
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92261802	234

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275213	60
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275213	56
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275215	1
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275215	30
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275215	57
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275215	5
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275217	90
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275217	119
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92275221	28
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274595	20
United Arab Emirates	701067941	VKMO 78000 #SQUADROX-i HMO 70000+VHK7000	92274595	22
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92224050	1
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92224050	7
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	25
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239360	2
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244485	20
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92249376	20
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253390	20
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255430	2
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256591	16
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266160	10
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273527	10
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274054	20
United Arab Emirates	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261648	30
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	20
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92241729	35
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92241729	20
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92246454	13
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92249683	12
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92249683	4
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92252107	166
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92252107	170
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250774	252

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250774	84
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92252109	135
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92252109	108
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92252108	262
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92252108	70
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250783	25
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255017	294
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254623	56
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92256410	119
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250790	294
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92256409	289
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92256409	1
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92257016	128
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92257017	68
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92257017	98
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258533	44
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	2
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258534	252
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251176	294
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259152	294
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	102
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	16
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259153	252
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251638	172
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251638	138
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262155	293
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262470	104
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262469	294
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262471	1
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263258	1
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263258	1
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264153	120
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264150	293

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264151	294
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254590	276
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254590	17
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271499	10
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261671	20
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261671	70
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261671	100
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275218	164
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275621	283
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275904	149
United Arab Emirates	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275903	294
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92228570	8
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92230632	12
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92230632	28
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92230632	10
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236492	15
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236492	13
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236492	28
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92236493	7
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92249684	8
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92250822	20
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92252187	10
United Arab Emirates	701067966	VKMO 50000 #SQUADROX-i HMO 50000+VHK7100	92252187	90
United Arab Emirates	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92223242	1
United Arab Emirates	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238925	20
United Arab Emirates	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92239359	25
United Arab Emirates	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92243775	25
United Arab Emirates	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92238928	35
United Arab Emirates	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92252035	231
United Arab Emirates	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92252113	39
United Arab Emirates	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	35
United Arab Emirates	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92261709	50
United Arab Emirates	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275932	41

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

United Arab Emirates	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275931	9
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232882	44
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232883	16
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232883	20
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232883	42
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92232883	20
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92221565	16
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92221565	20
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92233270	73
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92224050	24
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234236	11
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	15
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	5
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	63
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92234235	16
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92239361	40
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240737	6
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240737	25
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92240737	9
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230611	36
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92230611	30
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242276	40
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242276	39
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242276	12
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	20
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	12
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	36
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244484	40
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92244483	20
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92235776	2
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92242958	36
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	1
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92248443	24

Urgent!
Field Safety Notice (FSN)
-Annex I-
List of affected products country-/ region-specific



United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	2
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250746	12
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	24
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	20
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	16
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	24
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	28
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92252110	20
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253391	72
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253390	6
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253389	36
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92253981	16
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255444	1
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250749	28
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250749	20
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250754	25
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250754	28
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92250754	24
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256592	3
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256592	12
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256592	20
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255233	8
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255233	5
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260036	4
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260036	24
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260036	7
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260036	40
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260035	2
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260035	17
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260035	56
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260035	16
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256451	2
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92256451	5

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260967	3
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260967	24
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260967	11
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92260967	9
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92255935	2
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262090	3
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262090	3
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92262090	21
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264345	5
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264345	13
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264345	23
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264186	8
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	8
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	26
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92264344	12
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92266880	17
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	19
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	18
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	22
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	22
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92267476	8
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92261646	31
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268809	36
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268809	36
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268841	21
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269295	3
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	10
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	2
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92269714	12
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92257299	12
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92268840	46
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92270632	32
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273527	8

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	9
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	38
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92273561	22
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274054	16
United Kingdom	701067942	VKMO 70000 #SQUADROX-i HMO 70000+VHK7100	92274073	33
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	23
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	36
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	1
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230619	10
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232913	1
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	1
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	2
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	36
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	12
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	36
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	13
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	20
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92232914	50
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92236985	35
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92236985	10
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229776	22
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229776	6
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229776	21
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92229776	46
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92239555	73
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	36
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	11
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	12
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230622	42
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240741	1
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92241089	10
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	3
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	36

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	13
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	1
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240742	69
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92230623	8
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92235782	4
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92235782	36
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240162	14
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	7
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	27
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	6
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92240163	20
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250007	18
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250783	18
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92253979	1
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254624	18
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250785	4
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250776	18
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254623	39
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254623	13
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254623	13
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255009	17
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92255019	4
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258533	6
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258533	14
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92258533	7
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	7
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250781	20
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259063	4
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259063	18
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259063	19
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259063	12
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259063	15
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259063	4

Urgent!

Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	9
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	16
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92259154	2
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250777	21
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92250777	28
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262471	23
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92262509	3
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	10
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	11
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	36
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263171	16
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92263258	7
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92261669	20
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92253116	5
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	10
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92264348	15
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92251283	3
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	8
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	14
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	3
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92270887	8
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271499	29
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271499	28
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271499	25
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	6
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	41
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	20
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92271498	11
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272808	7
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272808	11
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272808	27
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272808	25
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92272808	23

Urgent!
Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274059	16
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274863	12
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274863	38
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274863	22
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274863	29
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274863	28
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275242	44
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275242	9
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275612	24
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275218	24
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275218	4
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	4
United Kingdom	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275929	32
United Kingdom	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92274222	24
United Kingdom	701067957	BE-VKMO 71000 #SQUADR-i HMO71000+VHK7100	92274222	60
United Kingdom	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92223242	14
United Kingdom	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	13
United Kingdom	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92229069	3
United Kingdom	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92259064	10
United Kingdom	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250837	3
United Kingdom	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92267036	2
United Kingdom	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92265489	3
United Kingdom	701068197	BO-VKMO 51000 #SQUADR-i HMO51000+VHK7100	92223245	16
Uruguay	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254624	47
Uruguay	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92254425	3
Uruguay	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92274863	100
Uruguay	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275193	100
Uruguay	701067949	VKMO 71000 #SQUADROX-i HMO 71000+VHK7100	92275622	90
Uruguay	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92250833	40
Uruguay	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92259064	10
Uruguay	701067969	VKMO 51000 #SQUADROX-i HMO 51000+VHK7100	92275625	30

Urgent!

Field Safety Notice (FSN)

-Annex I-

List of affected products country-/ region-specific



Please note: SSUs are called to actively find out whether the listed devices have been forwarded or sold into any other country. That country where the unit is currently located is also an affected country. Please send any information about forwarding and selling to other countries to: FSCA.cp@getinge.com.

We apologize for any inconvenience this may cause you and we will do our utmost to carry through this action as swiftly as possible.

For follow up actions, please contact us on FSCA.cp@getinge.com.

Sincerely,

Maquet Cardiopulmonary GmbH

Kehler Str. 31

76437 Rastatt

GERMANY