

August X, 2019

Olympus reference: QIL 152-005

URGENT FIELD SAFETY NOTICE

HANDLING INSTRUCTIONS FOR THE OLYMPUS MAJ-209 SINGLE-USE SUCTION VALVE

Attention: Operating Room Manager and Risk Management Department

| Model Name | Description | LOT No. on the carton box | LOT No. on the sterile pack |
|------------|-------------------------------------|---------------------------|--------------------------------|
| MAJ-209 | MAJ-209 Single-Use Suction Valve | 88H | H88 07 to H88 16 |
| | | 89H | H89 01 to H89 17 |
| | | 8XH | H8X 01 to H8X 22 |
| | | 8YH | H8Y 01 to H8Y 21 |
| | | 8ZH | H8Z 01 to H8Z 19 |
| | | 91H | H91 01 to H91 06 |

Dear Health Care Practitioner:

Olympus has become aware of a matter that requires your attention regarding the above-referenced LOT numbers of the Olympus MAJ-209 Single-Use Suction Valve ("MAJ-209"). The MAJ-209 has been designed to attach to the suction channel of bronchoscopes, cystoscopes, rhino-laryngoscopes and pleurascopes for aspirating fluid from the distal end of the endoscope through the instrument channel.

Please note that this second Field Safety Notice (FSN) is related to the first Field Safety Notice issued in March 2019 (Olympus reference: QIL 151-010).

As you may remember, Olympus initiated a first Field Safety Corrective Action (QIL 151-010) shortly after receiving a complaint of a MAJ-209 breaking during a patient procedure that then got stuck in the endoscope's suction cylinder. This resulted in an extended patient procedure and prolonged patient exposure to anesthesia. While no patient injury has been reported to date, a breakage of the MAJ-209 influences the fluid suction capability and could result in a potential vision decrease for the user and a possible procedure interruption.

Olympus thoroughly reviewed the recent complaint history of the MAJ-209 and determined that a change of the molding supplier led to the increased number of events. Meanwhile, the assessment showed that even those moldings do not break as long as they are used in accordance with the instructions. Hence, we reminded users that they can continue to use the MAJ-209 suction valves only in accordance with the Instruction for Use for MAJ-209 and the instructions within the addendum provided within the last FSCA.

In addition, Olympus ramped up the manufacturing capacities of the former molding supplier for a counter measured MAJ-209 Single-Use Suction Valve. As of today, and as a mere, additional precautionary measure, Olympus is enabled for a proper and timely replacement of the remaining affected lots in the field. We are now notifying our customers accordingly and ask them to return all remaining affected devices to Olympus.



Actions to be taken by the user:

Our records indicate that your facility has purchased one or more of these devices. Olympus requests your facility take the following immediate actions:

- a) Carefully read the content of this [FSN].
- b) Inspect your inventory for the MAJ-209 and identify any of the specified lot numbers.
- c) Return your inventory of the above mentioned lot numbers to your local Olympus organization at XXXXXX to get a free of charge replacement in return. Indicate on the enclosed questionnaire that you have received this notification as well as the quantities per LOT number you are going to return to Olympus for replacement.
- e) Send the completed form back to your Olympus representative (xxx)
- f) If you have further distributed this product, identify your customers, forward them this [FSN] including the attachments, and appropriately document your notification process.
- g) If you want to return affected products to Olympus, please contact your local Olympus representative at XXXX to discuss the timeline of receiving a replacement product.

Your National Competent Authority has been informed of this Field Safety Notice.

Olympus regrets any inconvenience caused and fully appreciates your prompt cooperation in addressing this situation.

If you require additional information or on-site support, please do not hesitate to contact Olympus directly at (XXX) XXX-XXXX from Monday till Friday or by e-mail at XXX.

Sincerely,



OLYMPUS URGENT FIELD SAFETY NOTICE HANDLING INSTRUCTIONS FOR THE OLYMPUS MAJ-209 SINGLE-USE SUCTION VALVE [Name & Address of Hospital/Medical Facility] [Dept/Attn] [Date] Quantities to be **Quantities still** LOT No. to be LOT No. on the LOT No. on the returned to available on stock returned to carton box sterile pack Olympus (please (please indicate if a **Olympus** indicate if a complete complete box or single box or single valves valves are still available. are returned) If no stock is available please insert 0) 88H **H88**07 to **H88**16 89H H8901 to H8917 8XH **H8X**01 to **H8X**22 8YH **H8Y**01 to **H8Y**21 8ZH **H8Z**01 to **H8Z**19

I herewith acknowledge the receipt of your Field Safety Notice (FSN).

Further I confirm that I have trained the responsible personnel on the actions required in the FSN for the MAJ-209 and transferred the information to all affected departments on which this action may have an impact. I confirm that I have no more affected LOTs on site besides the above mentioned quantities which I'll return to Olympus immediately.

91H

| Name (Signature) | |
|------------------|--|
| Name (Print) | |
| , , | |
| Position | |

Please fax this completed reply form to Olympus at [contact number] latest by XXXX

H9101 to **H91**06