

24th August 2012

FIELD SAFETY NOTICE

Oxoid Legionella BCYE Growth Supplement, SR0110C

Lot 1175209

Customers are to be advised of the following:

A technical investigation has confirmed that the lots of Oxoid Legionella BCYE Growth Supplement, SR0110C, Lot 1175209 may contain low level microbial contamination.

Continued use of this lot could result in incorrect results reporting.

Customers who have used this lot should review results reported and consider retesting and/or seek appropriate expert advice.

Accordingly, in keeping with our Quality Policy, we request that you destroy any remaining inventory of the lot listed above and contact Customer Services or your local Oxoid supplier who will issue a replacement.

This notice needs to be passed on to all who need to be aware within your organisation.

The Medicines and Healthcare products Regulatory Agency (MHRA) have been informed of this Field Safety Corrective Action.

If you experience any problems complying with this notice or you require any further information, please contact our Technical Support Department via our main switchboard on +44 (0)1256 841144.

Yours faithfully,



Colin Booth
Director, Regulatory Affairs Microbiology Europe and ROW

Microbiology

Oxoid Ltd.
Wade Road
Basingstoke

Hants
RG24 8PW
UK

+44 (0) 1256 841144 tel
+44 (0) 1256 814626 fax

www.thermofisher.com
www.oxoid.com