

13<sup>th</sup> November 2012

**FIELD SAFETY NOTICE**

**Oxoid Antimicrobial Susceptibility Testing Disc**  
**CIP5 CT0425B (Ciprofloxacin) Lot: 1220205**

Customers are to be advised of the following:

An investigation has indicated that boxes of this lot of Oxoid Antimicrobial Susceptibility Testing Discs CIP5 CT0425B (Ciprofloxacin) Lot: 1220205 may contain cartridges from a different production run i.e. AMP5 CT0827S Lot: 1220214.

The cartridges and individual discs are clearly labelled with the information for the AMP5 product and should be readily identified during routine use. We estimate that only a small number of boxes are impacted by this issue (< 0.7% of finished product; <11 boxes).

Customers should check stocks of this lot and if necessary contact Customer Services or your local Oxoid supplier who will issue a replacement.

This notice needs to be passed on to all who need to be aware within your organisation.

The Medicines and Healthcare products Regulatory Agency (MHRA) have been informed of this Field Safety Corrective Action.

If you experience any problems complying with this notice or you require any further information, please contact our Technical Support Department via our main switchboard on +44 (0)1256 841144.

Yours faithfully,



**Colin Booth**  
**Global Director, Quality Assurance and Regulatory Affairs, Microbiology Products**

Microbiology

Oxoid Ltd.  
Wade Road  
Basingstoke

Hants  
RG24 8PW  
UK

+44 (0) 1256 841144 tel  
+44 (0) 1256 814626 fax

[www.thermofisher.com](http://www.thermofisher.com)  
[www.oxoid.com](http://www.oxoid.com)