

## Important message to Customers,

Regarding Diluent GHI154, batch no 11171,12012 Diluent GHI154-2, batch no 11340 and 12094  $CaCl_2$  GHI155-2 batch no 12092  $CaCl_2$  GHI155-5 batch no 12011

Above Diluent and CaCl<sub>2</sub> is used for reconstitution of MediRox Owrens PT.

By commercial reasons we have decided to replace above lot numbers since investigations have confirmed that vials may contain a volume less than specified. Evaluations indicates a low fill level in less than 2% of the lot population.

The assessment is that there is no patient health risk using the product, but it may cause difficulties with abnormal controls and should therefore not be used. In case you have no possibility of replacing the product you can use it, provided that correct reconstitution volume first is verified.

MediRox will compensate all customers with new products upon contact. For replacement or questions please contact MediRox on order@medirox.se.

## MediRox AB

May 07, 2012

Linda Östling QA Manager Robert Löfvenmark, CEO