

[Insert CUSTOMER NAME] ATTN: RISK MANAGER [Insert CUSTOMER ADDRESS]

[Insert Date]

via Federal Express

URGENT MEDICAL DEVICE RECALL (Removal) IMMEDIATE ACTION REQUIRED

ACROBAT V Vacuum Off-Pump System and ACROBAT SUV Vacuum Off-Pump System
AXIUS XPOSE 3 Access Device and XPOSE 4 Access Device
Product manufactured from September 5, 2012 – June 19, 2014

| Customer Number | Institution Name |
|-----------------|------------------|
| customize | customize |

Dear Risk Manager,

This notification is to inform you of an urgent voluntary recall of the following:

| Product Name | Product Code/REF Number | | |
|------------------------------------|-------------------------|--|--|
| ACROBAT V Vacuum Off-Pump System | OM-9100S | | |
| ACROBAT SUV Vacuum Off-Pump System | OM-9000S | | |
| AXIUS XPOSE 3 Access Device | XP-3000 | | |
| XPOSE 4 Access Device | XP-4000 | | |

An internal finding identified the presence of pinholes/cuts in some of the tyvek pouches of the vacuum tubing sets included as an accessory to these products. As a result, there is a potential for the pouch integrity to be compromised, which may result in compromised sterility of the product. If the compromised product is used in surgery there is a potential risk of infection for the patient.

A review of our records indicates that you have received one or more of the units affected by this recall. Consistent with this voluntary recall; we are requiring the return of all of the products as listed in **Attachment 1** in this notification.

Please examine your inventory immediately to determine if you have any of the products listed. If so, please remove the affected products and place in a secure location.

This voluntary recall only affects the products listed; no other products are affected by this voluntary recall.

You must acknowledge receipt of this notification by completing and faxing back the attached Field Action Response form, whether or not you have any affected products.

Note: If you have acted as a **distributor** for any product from the lots listed, please immediately contact those accounts, advise them of the recall situation, and have them return any affected stock to you. Then complete the Field Action Response form attached.



We appreciate your understanding and thank you for your continued support. We apologize for any inconvenience or concern this may have caused.

If you have any questions, please contact your local MAQUET Medical Systems sales representative or our Customer Service at +1 408-635-0700.

Thank you for your cooperation and immediate assistance.

Sincerely,

Marylou Insinga

Specialist II, Regulatory Affairs and Field Action Compliance

MAQUET

45 Barbour Pond Drive

Wayne, New Jersey 07470

Email: Marylou.insinga@maquet.com



Attachment 1 Product List

| Attachment 1 Product List | | | | | |
|---------------------------|----------------------|--------------------|-------------------------|----------------------|-------------------|
| OM-9100S | OM-9000S | OM-9000S Cont'd | XP-3000 | XP-4000 | XP-4000 Cont'd |
| 25081363 | 25083285 | 25096305 | 25061930 | 25061406 | 25085516 |
| 25081832 | 25083405 | 25096404 | 25062239 | 25061961 | 25085696 |
| 25083629 | 25083504 | 25096913 | 25063171 | 25062341 | 25086333 |
| 25084722 | 25083904 | 25097097 | 25063264 | 25062853 | 25086530 |
| 25086515 | 25084006 | 25097336 | 25064005 | 25063026 | 25087192 |
| 25087723 | 25084498 | 25097417 | 25064805 | 25063351 | 25088336 |
| 25089063 | 25084648 | 25097747 | 25065216 | 25063594 | 25088517 |
| 25089942 | 25084928 | 25097801 | 25066072 | 25064160 | 25089557 |
| 25090685 | 25085094 | 25098540 | 25066261 | 25064428 | 25089623 |
| 25091907 | 25085850 | 25098968 | 25067242 | 25064917 | 25090324 |
| 25092783 | 25086057 | End of list | 25067493 | 25065315 | 25090692 |
| 25092968 | 25086330 | | 25067915 | 25065547 | 25091410 |
| 25093960 | 25086468 | | 25068869 | 25067036 | 25091811 |
| 25095207 | 25086786 | | 25070671 | 25067396 | 25092398 |
| 25096649 | 25086869 | | 25071619 | 25068245 | 25092567 |
| 25097068 | 25087249 | | 25072468 | 25068555 | 25093083 |
| 25097679 | 25087330 | | 25073684 | 25069189 | 25093570 |
| 25097895 | 25087412 | | 25075060 | 25069589 | 25094620 |
| 25098213 | 25087793 | | 25077055 | 25069971 | 25094845 |
| End of list | 25088394 | | 25077999 | 25070492 | 25095211 |
| | 25088704 | | 25078510 | 25070808 | 25095862 |
| | 25089154 | | 25078808 | 25071242 | 25097087 |
| | 25089224 | | 25080773 | 25072056 | 25097274 |
| | 25089724 | | 25081495 | 25072852 | End of list |
| | 25090578 | | 25082997 | 25073562 | |
| | 25090748 | | 25084179 | 25074441 | |
| | 25090943 | | 25086061 | 25075249 | |
| | 25091171 | | 25087498 | 25075644 | |
| | 25092128 | | 25088896 | 25076681 | |
| | 25092272 | | 25090502 | 25077208 | |
| | 25092690 | | 25090832 | 25077638 | |
| 1 | 25092813 | | 25091779 | 25078154 | , |
| | 25093167 | | 25092248 | 25079334 | |
| | 25093281 |] | 25092884 | 25079975 | |
| | 25094024 | | 25093619 | 25080256 | |
| | 25094065 | | 25094030 | 25080465 | |
| | 25094473 | | 25095768 | 25081324 | |
| | 25094712 | | 25096118 | 25081566 | |
| | 25094860 | | 25096687 | 25081959 | |
| | 25095107 |] | 25097508 | 25083287 | |
| | 25095600 | - | 25098402 | 25083699 | |
| | 25095769 25096128 | 1 | 25098904 End of list | 25084533 25085038 | |
| | 20090120 | | LIIU OI IISL | 25005030 | |