

19th October 2017

Soren Soes
Thermo Fisher Diagnostics ApS
Microbiology
Gydevang 33, DK-3450 Allerød
Org. No.: 27640745
Denmark

URGENT FIELD SAFETY NOTICE

Re : ThermoScientific™ Oxoid™ Mueller-Hinton Broth, CM0405B Lots 1833157 (D.O.M 09.03.2016) and 1865331 (D.O.M 18.05.2016)

Dear Soren,

Customers are to be advised of the following:

DESCRIPTION

An internal technical investigation by Oxoid Limited, part of Thermo Fisher Scientific, has confirmed that ThermoScientific™ Oxoid™ Mueller-Hinton Broth, CM0405B Lots 1833157 and 1865331 have incorrect cation information detailed on the product label.

Please refer for Field Safety Notice for full details.

We request that you destroy any remaining inventory of the above.

Customers should be sent a copy of the Field Safety Notice and an Acknowledgment Form to confirm receipt of the notice. We require confirmation of the sold to parties and either a copy of the customer confirmation form or a summary of the sold to parties and customer confirmation.

This information together with replacement requests should be sent to Martyn Rogers European Quality Director by **16th November 2017**. If you have any difficulty or delay in complying with this request please contact the Technical Support Department on +44 (0)1256 694238, or at microbiology.techsupport.uk@thermofisher.com.

Please confirm receipt of this notification by e. mail to Martyn.Rogers@thermofisher.com alternatively fax 01256 814626.

Yours sincerely,



Martyn Rogers
European Quality Director
Thermo Fisher Scientific, Microbiology Basingstoke