

Urgent!
Field Safety Notice (FSN)
-Annex I-
List of affected products country-/ region-specific



This Annex I is considered as a supplementary attachment to the Field Safety Notice of FSCA-2018-03-27

FSCA Number: 2018-03-27

FSCA Title: Arterial Cannula – broken vent plug

Affected Product: Products including 3/8” vent plug (70000.8256)
(see list below)

Affected Timeframe: Non-coated: March 2015 up to now
Coated: March 2016 up to now

List of affected products in Denmark, Finland, Norway and Sweden			
Country		Material	Qty.
Denmark	70100.2206	A20-0101#Arterielle Kanüle	10
	70100.2466	ASR 18 V#Arterielle Kanüle	20
Finland	70100.2222	A20-7101#Arterielle Kanüle	90
Norway	70100.2234	A22-2105#Arterielle Kanüle	10
Sweden	70100.2400	INACTIVE AS 21 V -85 B#Arterial Cannula	40
	70100.2408	INACTIVE AS 24 V -85 B#Arterial Cannula	40

Please note: SSUs are called to actively find out whether the listed devices have been forwarded or sold into any other country. That country where the unit is currently located is also an affected country. Please send any information about forwarding and selling to other countries to:
FSCA-2018-03-27.cp@getinge.com

We apologize for any inconvenience this may cause you and we will do our utmost to carry through this action as swiftly as possible.

Urgent!
Field Safety Notice (FSN)



-Annex I-

List of affected products country-/ region-specific

For follow up actions, please contact us on FSCA-2018-03-27.cp@getinge.com

Sincerely,

Maquet Cardiopulmonary GmbH
Kehler Str. 31
76437 Rastatt
GERMANY