+44 191 419 4488 Tel: Fax: +44 191 419 5693

Email: regulatoryaffairs@rocketmedical.com Web:

www.rocketmedical.com



ROCKET MEDICAL PLC - SRN: GB-MF-000025375

# **Urgent Field Safety Notice NVFSN-10 Rocket Seldinger Chest Drain Kit**

16 OCT 2025

Dear Customer,

Rocket Medical is issuing this Field Safety Notice regarding the devices listed in Table 1. Our records indicate that you have one or more of these devices.

Affected Product Codes: R54544-12-SG, R54544-18-SG, R54544-12-PK, R54544-18-PK, R54549-16-PK and R54549-20-PK



SG Seldinger Chest Drainage Kit



PK Seldinger Chest Drain Kit

Tel: +44 191 419 4488 Fax: +44 191 419 5693

Web:

Email: regulatoryaffairs@rocketmedical.com

www.rocketmedical.com



Product Code(s)	Product Description(s)	Affected	l LOT(s)	Basic-UDI(s)
		496708	501186	
		496903	501548	
		497147	502122	
	Rocket 12Fg Seldinger Catheter Procedure Tray	497292	502317	
		497344	502534	
		497664	502949	
		499226	503201	
R54544-12-PK		499276	503429	
104044-12-11X		499415	503732	
		499462	503899	
		499806	503935	
		499902	504283	
		500404	504581	
		500474	504637	
		500757	504821	
		500955	505025	
	Rocket 12Fg Seldinger Catheter with Safety Guard	497012	502660	05055070075000000
		497561	502780	
		497763	502978	050552709TF06DXY
		498069	503202	
		499335	503384	
		499541	503406	
R54544-12-SG		499903	503536	
		500405	503733	
		500630	503900	
		500706	504179	
		500812	504397	
		501030	504628	
		501615	504822	
R54544-18-PK	Rocket 18Fg Seldinger Catheter Procedure Tray	496899	500956	
		497076	501169	
		497584	501188	
		499227	502430	
		499417	502951	
		499461	503306	
		499897	503430	
		499898	503529	

Tel: +44 191 419 4488 Fax: +44 191 419 5693

Email:

Web:

regulatoryaffairs@rocketmedical.com

www.rocketmedical.com



	T		
		499899	504180
		499908	504543
		500407	504823
		500477	
		496809	501616
	Rocket 18Fg Seldinger Catheter with Safety Guard	497346	501710
		497665	502431
R54544-18-SG		498972	503735
		499909	503937
		500782	504573
		501256	504824
		496659	497629
R54549-16-PK	Rocket 16Fg Seldinger Catheter Procedure Tray	496918	499814
		497077	500408
		496455	499910
R54549-20-PK	Rocket 20Fg Seldinger Catheter Procedure Tray	496811	500480
		496919	501734
		497516	503706
		499083	504152

Table 1

# Description of the problem:

The Instructions for Use (IFU) (ZDOCK180) for the devices listed above contains the instruction "The chest tube can now be secured to the skin by using the fixation device R54960-PG-FX or suture or both and is ready for connection to a suitable sealed drainage system such as the Rocket Blue Bottle or Rocket Ambulatory Bag". The fixation device mentioned is no longer supplied by Rocket Medical and Rocket Medical determines that securing the device by suture is a mandatory action to prevent risk of disconnection.

The IFU has been updated to include revised guidance regarding the need for a suture, in steps 14 and 15. The updated text now states: "The chest tube must now be secured to the skin by suture and is ready for connection to a suitable sealed drainage system such as the Rocket Blue Bottle or Rocket Ambulatory Bag. Further support to the catheter can be provided by the fixation device."

The revised IFU is attached to this communication, and we kindly ask that you read it carefully to ensure continued safe and effective use of the device.

Tel: +44 191 419 4488 Fax: +44 191 419 5693

Email: regulatoryaffairs@rocketmedical.com Web:

www.rocketmedical.com



## **Actions Required by Customers:**

We understand that you received the above referenced product(s) and therefore request that you follow the steps listed below:

- Ensure a copy of this FSN and the updated IFU is available to all users or potential users of this device
- the FSN acknowledgment form at the end of this document and return to: CustomerServices@rocketmedical.com

### Stock Instruction:

Stock is not affected; no action is required.

Rocket Medical PLC. does not expect any disruption in the supply of this device as a result of this issue.

We have notified the relevant regulatory authorities of this issue and resulting Field Safety Corrective Action.

Your cooperation in this matter is greatly appreciated. We would like to sincerely apologise for the inconvenience caused by this issue and thank you for your continued custom. If you have any questions on this issue, please contact your Rocket Medical sales representative.

Yours sincerely,

Laura Hutchinson Head of Quality and Regulatory Affairs Rocket Medical Plc.

Tel: +44 191 419 4488 Fax: +44 191 419 5693

Email: regulatoryaffairs@rocketmedical.com Web:

www.rocketmedical.com



# **Customer Acknowledgement Form**

Please complete this form even if you have not seen this issue

Product Code(s)	Product Description(s)	Affected LOT(s)	Basic-UDI(s)
		496708 501186	
		496903 501548	
		497147 502122	
		497292 502317	
		497344 502534	
		497664 502949	
		499226 503201	
R54544-12-PK	Rocket 12Fg Seldinger Catheter	499276 503429	
NJ4J44-12-FN	Procedure Tray	499415 503732	
		499462 503899	
		499806 503935	
		499902 504283	
		500404 504581	
		500474 504637	
		500757 504821	
		500955 505025	
	Rocket 12Fg Seldinger Catheter	497012 502660	050552709TF06DXY
		497561 502780	
		497763 502978	
		498069 503202	
		499335 503384	
		499541 503406	
R54544-12-SG		499903 503536	
	with Safety Guard	500405 503733	
		500630 503900	
		500706 504179	
		500812 504397	
		501030 504628	
		501615 504822	
R54544-18-PK	Rocket 18Fg Seldinger Catheter	496899 500956	1
		497076 501169	
		497584 501188	
	Procedure Tray	499227 502430	
		499417 502951	

Tel: +44 191 419 4488 Fax: +44 191 419 5693 Email: regulatoryaffairs@

Web:

regulatoryaffairs@rocketmedical.com

www.rocketmedical.com



		499461 503306	
		499897 503430	
		499898 503529	
		499899 504180	
		499908 504543	
		500407 504823	
		500477	
		496809 501616	
R54544-18-SG	Rocket 18Fg Seldinger Catheter with Safety Guard	497346 501710	
		497665 502431	
		498972 503735	
		499909 503937	
		500782 504573	
		501256 504824	
		496659 497629	
R54549-16-PK	Rocket 16Fg Seldinger Catheter	496918 499814	
	Procedure Tray	497077 500408	
R54549-20-PK	Rocket 20Fg Seldinger Catheter	496455 499910	
		496811 500480	
	Procedure Tray	496919 501734	
	1 1000ddie 11ay	497516 503706	
		499083 504152	

On behalf of this organisation, I acknowledge that I have read and understood this FSN, completed the indicated actions and that the information will be displayed in a prominent position within the appropriate clinical environment for a minimum of one month from the date of receipt.

# Organisation Location (Country) Address Email Telephone no. Name Position no. Signature Date

# Return completed forms by email to:

**Number of Units in Affected LOTs:** 

Tel: +44 191 419 4488 Fax: +44 191 419 5693

Email: regulatoryaffairs@rocketmedical.com Web:

www.rocketmedical.com



Name	David Ashby	
Position	Regulatory Affairs Manager	
Organisation	Rocket Medical PLC	
Email	CustomerServices@rocketmedical.com	
Subject of email	ect of email URGENT FIELD SAFETY NOTICE Seldinger Chest Drainage Kit	