

The Diagnostic Specialist

DiaSorin S.p.A. Via Crescentino, snc 13040 Saluggia (VC) Italy tel. +39 / 0161.487093 fax +39 / 0161.487628 www.diasorin.com

Urgent Field Safety Notice

Urgent Field Safety Notice

Commercial name of the affected product: LIAISON® Control anti-HBc

FSCA-identifier (e.g. date): December 18th, 2013

Type of action (e.g. definition of a FSCA): In Field Safety Corrective Action to destroy remaining inventory

Date: December 18th, 2013

Attention: Immediately stop using the below reported device and destroy any remaining inventory.

Details on affected device:

Type of device: In Vitro Diagnostic Medical Device

Model name LIAISON® Control anti-HBc Catalog – 310131

Batch/serial number 068033X and 068033X/1

Expiry date: February 18th, 2014

Description of the problem:

Internal testing confirmed that an increased frequency of control positive values recovering out of the defined limit may occur when running the LIAISON® Control anti-HBc lot n. 068033X. As a consequence the run cannot be validated.

Advise on action to be taken by the user:

- Stop using the device
- Identify and dispose the device.
- Fill the confirmation form to be sent back to the manufacturer

Transmission of this Urgent Field Safety Notice:

This notice needs to be passed on all those who need to be aware within your organisation or to any organisation where the potentially affected devices have been transferred.

Please transfer this notice to other organisations on which this action has an impact.



The Diagnostic Specialist

DiaSorin S.p.A. Via Crescentino, snc 13040 Saluggia (VC) Italy tel. +39 / 0161.487093 fax +39 / 0161.487628 www.diasorin.com

Contact reference person:

Name: Antonella Fassio

Organisation: DiaSorin S.p.A

Address:

Via Crescentino s.n.c.

13040 Saluggia (VC) Italy

Contact details:

E-mail: antonella.fassio@diasorin.it

Tel. +39.0161.487.849

1 .	C	.11 .		1	1	1	. 1	•	D 1 1	A
a lindaggian	CONTINUO	that thic	notion	200	haan	notition	tha	ONNEONEIGTO	PACILIATORS	Acanon
 e undersign	COMMITTEE	IIIAI IIIIS	11011111	11/45	1100011	110111111111111111111111111111111111111	1110	annicioni iaic	KEYMAIOIV	ASCILV
 e dilacion,	Commi	tilde tillo	HOULE	IIU	CCCII	HOUHHOU	CIIC	appropriate	I to Suitatoi	

Signature		
Signature		



The Diagnostic Specialist

DiaSorin S.p.A. Via Crescentino, snc 13040 Saluggia (VC) Italy tel. +39 / 0161.487628 fax +39 / 0161.487628 www.diasorin.com

This section has to be filled in by the customer and returned to DiaSorin S.p.A.

Product:	
Kit Lot:	
RETURN TO FAX No:	
RETURN BY MAIL TO:	
(Please use capital letters)	
NAME:	
INSTITUTION:	
KITS USED, No:	
	☐ KITS DESTROYED, No
KITS REMAINING, No	
	☐ KITS SENT BACK TO DiaSorin S.p.A, No
DATE:	
SIGNATURE:	
CEAI.	