Spiggle & Theis Medizintechnik GmbH, Burghof 14, D-51491 Overath

Adressat:

Markus Ratschinski

Our Sign: MR

51491 Overath, Germany Burghof 14

Tel.: +49 (0) 22 06 - 90 81 23 Fax: +49 (0) 22 06 - 90 81 13 m.ratschinski@spiggle-theis.de

July 17th, 2014

## Field Safety Notice

## PTFE Ventilation Tubes of Spiggle & Theis Medizintechnik GmbH regarding

Article-No. (REF)	Batch-No. (LOT)
104100	201308121240, 201309030100, 201311150080,
	A01306171000, 201311150220
104100F	201308120240
104115	201306171500, 201308081490, 201309030350,
	B01401281500, 201311150150, 201308120600,
	201308120990, 201311150060, 201311190160,
	A01311150080, 201311150120, 201304121000
104115F	201308121500, 201311190020, 201311190120,
	201312090900, 201312092100, 201311190130
104125	201306171000, 201311150230, 201311150430,
	201308120490, 201311150110, A01311150230,
	201311150390, 201308260380, A01309030100
104125F	201308120140, 201311190040
104150	201308290130, 201308260001
104200	201306140350, 201311150020, 201311150030,
	201308290090
104210	201312030700, 201311150360, A01311150060,
	201307120300, 201308120540, A01312030700,
	B01311150060
104311	201308262360, 201311193740, 201308121700

BLZ: 370 626 00 Kto.-Nr.: 1500 239 014 VR-Bank Bergisch Gladbach

Kto.-Nr.: 306 217 BLZ: 500 502 01 Frankfurter Sparkasse 1822

1 of 3

IBAN: DE57 5005 0201 0000 3062 17 BIC: HELADEF1822



Dear Sir or Madam,

This communication is to inform you of a potentially affected weld seam of the blister packaging of the aforementioned PTFE ventilation tubes.

Within the scope of internal routine checks we discovered, that the weld seam of the blister packagter cavity might show a visually inconsistent blue coloring (see pictures). ing might be incomplete in the area of the pull tab. Apart from that the weld seam around the blis-





which in turn is within a blister. ventilation tubes are protected by two packaging barriers - the product is within a micro container, No microbial contamination and thus no potential infection of patients is to be feared, since the

age (blister), before using the above-mentioned ventilation tubes, as specified in our instructions far. However, we would still like to ask you to examine the integrity of each individual sterile pack-Furthermore we have not received any customer feedback regarding the above described sealing so

damage may impair the sterility of the product." damage to the packaging will render the product useless. Do not open the protective packaging until just before you wish to remove the product. Before opening, inspect packaging and weld seams for damage since any "Any contamination of the product must be avoided. Store the product in its sealed protective packaging. Any

Please withdraw blisters, where the sterile barrier appears to be impaired (see pictures above) and info@spiggle-theis.de) products. Please contact our customer service in this regard (Tel.: +49 (0) 2206 90 81 0 / email: return them to us, we recommend you not to use these products. Of course, we will replace relevant

All other products can be used safely and without restriction.



who were treated with a ventilation tube that may have been packed in such a blister. According to a risk assessment, we conclude that no additional risk is to be expected for patients

The integrity of the sterile packaging in future deliveries is secured throughout by corrective measures, already initiated and implemented by us.

parties, please forward a copy of this information. relevant persons are aware of this Field Safety Notice. If you have delivered the products to third Please make sure that within your organization all users of the aforementioned products and other

Please keep this information sheet at least until the action has been completed

BfArM (German Competent Authority) has been informed of this Field Safety Notice.

sense of general patient well-being. We apologize for the inconvenience caused. However, we consider this measure necessary in the

Of course we are at your disposal for any questions or further information you may have.

- . Our safety officer Mr. Markus Ratschinski via phone +49 (0) 2206 90 81 23 or via email m.ratschinski@spiggle-theis.de.
- . or via E-Mail t.nuesse@spiggle-theis.de. Our contact person quality management Mr. Thomas Nüsse via phone +49 (0) 2206 90 81 26
- . Our customer service via phone +49 (0) 2206 90 81 0 or via E-Mail info@spiggle-theis.de in case of a replacement delivery

Best regards

## Spiggle ႙ၟ၀ Theis

Medizintechnik GmbH

(Managing Director/ Safety Officer) Markus katschinski

Inomas Nusse