

performancehealth.co.uk

Main: +44 (0) 3448 730 035

Fax: +44 (0) 1623 557 769

Nunn Brook Road, Huthwaite, Sutton-in-Ashfield, Nottinghamshire, NG17 2HU, UK.

Field Safety Notice

Patterson Walking Frames - All models supplied between June and November 2017 (Batch codes DMW23/2017 – DMW46/2017 inclusive)

It has come to our attention that a small number of Patterson Walking Frames (both wheeled and non-wheeled) are arriving at customers with the pins from the spring clips in the height adjustable legs having broken off. This has not yet been isolated to a particular batch(s) due to the low number of returns. As a precaution, we are including frames manufactured in the previous six months within this notice.



Batch codes DMW23/2017 - DMW46/2017

ACTION REQUIRED: As a precautionary measure and in accordance with the information within our instructions for use (height adjustment section), please ensure you make the following checks before issuing a walking frame to a patient:

Ensure that each leg has both spring clip pins present in the front and rear legs. If a spring clip pin is missing (see photos below), please contact Performance Health (details on page 4) in order to arrange a return. Any walking frames found with missing spring clip pins on the spring clips will be replaced or credited, as preferred.

> Company Registration No. 4374752 VAT Registration No. 945765283





SammonsPreston





























performancehealth.co.uk

Main: +44 (0) 3448 730 035

Fax: +44 (0) 1623 557 769

Nunn Brook Road, Huthwaite, Sutton-in-Ashfield, Nottinghamshire, NG17 2HU, UK.




Image 1 - Both spring clip pins present



Image 2 - One spring clip pin missing

Company Registration No. 4374752 VAT Registration No. 945765283


































Image 3 – Appearance of frame with missing pin and pin present

If during these checks you find the above issues or any other fault with the walker please contact our **customer services** on **03448 730 035** for advice.



performancehealth.co.uk

Main: +44 (0) 3448 730 035 Fax: +44 (0) 1623 557 769 Nunn Brook Road, Huthwaite, Sutton-in-Ashfield, Nottinghamshire, NG17 2HU, UK.

Field Safety Notice

Patterson Walking Frames - All models supplied between June and November 2017 (Batch codes DMW23/2017 – DMW46/2017 inclusive)

Reply Letter

I can confirm we have inspected the product and codes described in the FSN and have none of these items / have checked (delete as applicable) as requested.

Hospital / Customer name
Account number
Name of person responding
Position
Date

Please complete this form and return to Customer Services at Performance Health by email international@performancehealth.com or fax back 03448 730 100





























