

Siemens Healthcare GmbH, SHS DI XP M&S, Siemensstr. 3, 91301 Forchheim

<To the person in charge of the unit where the SIEMENS product is operated in conjunction with sterile plastic bushings from TURON MEDTECH AB, and the administrative head of organization>

Name Department Michael Zeus SHS DI XP M&S SHS DI XP QT

Telephone Fax Mobile E-mail

Date

January 29, 2020

## Field Safety Notice from and on behalf of TURON MEDTECH AB for sterile plastic bushings

Dear Ladies and Gentlemen,

One of our key principles at Siemens Healthineers is that we do not compromise on quality. Quality is key and therefore it is our responsibility to inform you that there is an official Field Safety Notice (FSN) from one of our suppliers.

This safety notice only applies to you if you are using sterile plastic bushings from TURON MEDTECH AB with the Biopsy Unit from our Women's Health portfolio.

Please find all relevant information in the attached Field Safety Notice from TURON MEDTECH AB and follow the given instructions.

For further questions regarding the plastic bushings, please contact TURON MEDTECH AB directly using the contact information provided in the FSN.

For all other questions regarding Siemens Healthineers products please contact your responsible sales representative, your partner in providing healthcare services and improving patient experience. We regret the inconvenience caused by this issue.

Sincerely yours,

Siemens Healthcare GmbH

Michael Zeus
Vice President Marketing & Sales

X-Ray Products

Dr. Christian Denger Vice President Quality

X-Ray Products

Management: Bernhard Montag, President and Chief Executive Officer; Jochen Schmitz, Christoph Zindel Siemensstr. 3 91301 Forchheim Germany Tel.: +49 (9191) 180 siemens.com/healthcare